



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

APR 20 2016

Date of Test 04-20-2016 Operator Redwolf Production API #30-0 45-05538

Property Name Manrose Well No. 1 Location: Unit I Section 2 Township 25 Range 8

Well Status(Shut-In or Producing) Initial PSI: Tubing 37 Intermediate NA Casing 37 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead	INTERM			
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>Ø</u>	<u>NA</u>	<u>37</u>		
10 min	<u>Ø</u>	<u>↓</u>	<u>37</u>		
15 min	<u>Ø</u>	<u>↓</u>	<u>37</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing <u>X</u>	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD Opsi. INTERMEDIATE _____

REMARKS:

Well is shut in. BH had nothing when opened - Ops.

By Brian E. DePue

Witness _____

(Position)

E-mail address _____