



NEW MEXICO ENERGY, MINERALS  
and  
NATURAL RESOURCES  
DEPARTMENT

OIL CONS. DIV DIST. 3

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178  
FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

MAY 03 2016

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-3-2016 Operator Conoco/Burlington API # 30-039-30229

Property Name San Juan 27-4 Unit Well No. 132N Location: Unit H Section 27 Township 27 Range 4

Well Status ~~(Producing)~~ or (Producing) Tubing 192 Intermediate 0 Casing 188 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:				
	BRADENHEAD	INTERMEDIATE	CASING	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes	<u>✓</u>	<u>Ø</u>	<u>188.3</u>	Steady Flow	
10 minutes	<u>✓</u>	<u>Ø</u>	<u>188.9</u>	Surges	
15 minutes	<u>✓</u>	<u>Ø</u>	<u>189.5</u>	Down to Nothing	
20 minutes				Nothing <u>✓</u>	<u>✓</u>
25 minutes				Gas	
30 minutes				Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ✓ FRESH ✓ SALTY ✓ SULFUR ✓ BLACK ✓

5 MINUTE SHUT-IN BRADENHEAD Ø INTERMEDIATE Ø

REMARKS:

Nothing on BH when opened. - Nothing on intermediate when opened  
casing climbed a bit

By Jerry White  
(Position)

Witness J K H NMOC

E-mail address \_\_\_\_\_