## OIL CONS. DIV DIST. 3

MAY 0 4 2016

NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/DistrictIII/3distric.htm

## BRADENHEAD TEST REPORT

(Submit 1 copies to above address)

Date of Test	4/15/2016 Dunn					Encana			API #30-0			39-25507		
Property Name							19	Location: Unit	Н	_Section _	4			
Pressure (Shut-	In or Producing) Shut in			Tubing				Intermediate	NA	Casing	169			
ESTING	P		PRESSURES		NTERMEDIA	те то	ATMOS	PHERE INDIVIDUA	ALLY 1	FOR 15 MI		EACH ADENHEAD	IN	FERMEDIATE
TIME	ВН	INT	CSG	INT	CSG							FLOWED		FLOWED
minutes	0		169					Steady Flow						
0 minutes	0		169					Surges						
5 minutes	0		169					Down to Nothing	g					
0 minutes								Nothing		-	х			-/
5 minutes								Gas						
0 minutes								Gas & Water						
								Water						
f bradenhead	flowed was	ter, check a	ill of the des	criptions t	hat apply b	elow:								
CLEAR	FRESH				SALTY			SULFUR	BLACK					
REMARKS:				TE SHUT-IN BRADENI			AD 0 INTERMEDIATE							
ty	Lee Robbins						Witness							
	Foreman						_							
-														