

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

MAY 11 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report



Name of Company Burlington Resources, a Wholly Owned Subsidiary of ConocoPhillips Company	Contact Lisa Hunter
Address 3401 East 30th St, Farmington, NM	Telephone No. (505) 258-1607
Facility Name: Mangum 12	Facility Type: Gas Well
Surface Owner Fee	Mineral Owner Federal (NM-020982) API No. 3004525806

LOCATION OF RELEASE

Unit Letter E	Section 33	Township 29N	Range 11W	Feet from the 1707	North/South Line North	Feet from the 380	East/West Line West	County San Juan
-------------------------	----------------------	------------------------	---------------------	------------------------------	----------------------------------	-----------------------------	-------------------------------	---------------------------

Latitude **36.68484** Longitude **-108.00402**

NATURE OF RELEASE

Type of Release Natural Gas	Volume of Release 106 Mcf	Volume Recovered 0
Source of Release Well Head - Vandalism	Date and Hour of Occurrence 05/02/16 @ 7:25 a.m.	Date and Hour of Discovery 05/04/16 @ 1:25 p.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken* Vandalism – Lubricator was found lying on the ground next to the wellhead assembly.		
Describe Area Affected and Cleanup Action Taken.* No further remediation required.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Lisa Hunter	Approved by Environmental Specialist: 	
Title: Field Environmental Specialist	Approval Date: 5/12/2016	Expiration Date:
E-mail Address: Lisa.Hunter@cop.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: May 5, 2016 Phone: (505) 258-1607		

* Attach Additional Sheets If Necessary

NC51613033865