



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

MAY 16 2016

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5/16/2016 Operator COPC API #30-0 39-20339

Property Name Creek Well No. 1 Location: Unit G Section 4 Township 29 Range 5

Well Status (~~Shut-In~~ or Producing) Initial PSI: Tubing 98 Intermediate — Casing 136 Bradenhead 74

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0	—	136		
10 min	0	—	137		
15 min	0	—	137		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	✓
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR — FRESH — SALTY — SULFUR — BLACK —

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 1 INTERMEDIATE —

REMARKS:

Bradenhead blew down to a slight blow in 2 min 15 sec.
down to fumes in 10 min. ~~5~~

By Robin Danks

Witness Paul Wake

(Position)

E-mail address —