

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

MAY 16 2016

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

## OPERATOR

☒ Initial Report ☒ Final Report

Name of Company: BP	Contact: Steve Moskal
Address: 200 Energy Court, Farmington, NM 87401	Telephone No.: 505-326-9497
Facility Name: Pritchard C 001	Facility Type: Natural gas well
Surface Owner: Federal	Mineral Owner: Federal
API No. 3004528622	



## LOCATION OF RELEASE

Unit Letter G	Section 34	Township 31N	Range 09W	Feet from the 1,430	North/South Line North	Feet from the 1,540	East/West Line East	County: San Juan
------------------	---------------	-----------------	--------------	------------------------	---------------------------	------------------------	------------------------	------------------

Latitude 36.85802° Longitude -107.76444°

## NATURE OF RELEASE

Type of Release: natural gas	Volume of Release: 400 mcf	Volume Recovered: none
Source of Release: Dump valve to BGT	Date and Hour of Occurrence: 5/09/2016 @ 12:00 PM	Date and Hour of Discovery: 5/10/2016 @ 12:00PM AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* BP representative found water dump controller hung open to the low side of the separator with gas venting out of the low side into the production pit.		
Describe Area Affected and Cleanup Action Taken.* Hung dump valve vented directly to below grade tank and atmosphere. No action necessary outside of repair/adjustment of dump valve.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Steve Moskal	Approved by Environmental Specialist: 	
Title: Field Environmental Coordinator	Approval Date: 5/17/2016	Expiration Date:
E-mail Address: steven.moskal@bp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: May 16, 2016	Phone: 505-326-9497	

\* Attach Additional Sheets If Necessary

NVF1613852763

①