



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONS. DIV DIST. 3

JUN 07 2016

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6/7/2016 Operator Parko Oil API #30-0 43-05185  
Property Name Chapman Well No. 1 Location: Unit N Section 20 Township 23 Range 6  
Well Status (Shut-In or Producing) Initial PSI: Tubing 70 Intermediate NA Casing 70 Bradenhead D

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead Int	Csg	INTERM Int	Csg
TIME					
5 min	<u>D</u>		<u>70</u>		
10 min	<u>D</u>		<u>70</u>		
15 min	<u>D</u>		<u>70</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing <u>X</u>	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD D INTERMEDIATE NA

REMARKS:

BH Blew down in 3 sec through 1" valve

By Johnny Lopez  
Pumper  
(Position)

Witness Jonathan D. Kelly

E-mail address \_\_\_\_\_