

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

JUN 08 2016

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company WPX Energy Production	Contact Deborah Watson
Address PO Box 640	Telephone No. 505.333.1880
Facility Name MC 2 Com #283H	Facility Type Well Site
Surface Owner BLM	Mineral Owner BLM/Navajo
API No. 30-045-35608	



LOCATION OF RELEASE

Unit Letter L	Section 4	Township 23N	Range 8W	Feet from the 2431	North/South Line South	Feet from the 405	East/West Line West	County San Juan
---------------	-----------	--------------	----------	--------------------	------------------------	-------------------	---------------------	-----------------

Latitude 36.255977 Longitude -107.695452

NATURE OF RELEASE

Type of Release Crude oil/produced water	Volume of Release 12 BBLS	Volume Recovered 4 BBLS
Source of Release: Blow down valve on compressor dump line	Date and Hour of Occurrence May 29, 2016 unknown	Date and Hour of Discovery May 29, 2016 8:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* A 1-inch blow down valve on the compressor dump line header was accidentally left open. On May 29, 2016, a spec truck recovered 4 bbls of freestanding fluids and a construction crew removed a portion of the impacted gravel and soil.		
Describe Area Affected and Cleanup Action Taken.* Spilled fluids were contained on the location. <ul style="list-style-type: none"> • Spec truck recovered 4 bbls of freestanding fluid on May 29, 2016. • On May 29, 2016, a portion of the impacted soil and gravel was removed and transported to the landfarm for disposal. • Remaining impacted soil and gravel will be excavated and transported to the landfarm for disposal. • A confirmation sample will be collected and analyzed for BTEX, TPH (GRO/DRO), and chlorides. • Additional cleanup actions will be taken if analytical laboratory results exceed NMOCD action levels based on site ranking. • Results will be included in the Final C-141 report. 		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Deborah Watson	Approved by Environmental Specialist: 	
Title: Environmental Specialist	Approval Date: 06/09/2016	Expiration Date:
E-mail Address: Deborah.watson@wpxenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 6/7/16 Phone: 505-333-1880	NMF 1616039616	

* Attach Additional Sheets If Necessary

please provide notice to
NMOCD to allow witnessing
of sample.

D