



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONS. DIV DIST. 3

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
[http://emrdd.state.nm.us/ocd/District III/3district.htm](http://emrdd.state.nm.us/ocd/District%20III/3district.htm)

JUN 16 2016

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

MAY 04 2016

Date of Test 5/4/2016 Operator La Plata Gathering API #30-0 39-23832

Property Name Foster Well No. 1 Location: Unit 6 Section 8 Township 25 Range 7

Well Status(Shut-in or Producing) Initial PSI: Tubing 81 Intermediate — Casing — Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing TIME	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
5 min	0	—	81		
10 min	0	—	81		
15 min	0	—	81		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR — FRESH — SALTY — SULFUR — BLACK —

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE —

REMARKS:

Slim hole, tubing is casing. nothing on bradenhead.

By Glen A. Hise

Witness Paul Wicks

Less Operator  
(Position)

E-mail address glen.hise@wapii-svc.com