



NEW MEXICO ENERGY, MINERALS  
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505 334-6178 FAX: (505) 334-6170  
<http://www.emnrd.state.nm.us/ocd/>

**BRADENHEAD TEST REPORT**  
(Submit 2 copies to above address)

OIL CONS. DIV DIST. 3

DEC 18 2015

Date of Test 9/14/15 Operator BP America Production Company API # 3004511618  
Property Name GCU 213-DK Location: Unit J Section 8 Township 28 Range 12  
(Well Name and Number)  
Pressure (Shut-in or Producing) Tubing 189 Intermediate - Casing 210 Bradenhead 37

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	0	210	S	S		Steady Flow	
10 minutes	0	210				Surges	
15 minutes	0	210				Down to Nothing	✓
20 minutes						No Flow	
25 minutes						Gas	
30 minutes						Gas and Water	
5 minute SI	0	210				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear \_\_\_\_\_ Fresh \_\_\_\_\_ Salty \_\_\_\_\_ Sulfur \_\_\_\_\_ Black \_\_\_\_\_

5 Minute Shut-in Bradenhead 0 Intermediate \_\_\_\_\_

REMARKS:

Blew from 1" valve. Btl blew to nothing in 45 sec.

By [Signature] Witness \_\_\_\_\_

(Position)