

State of New Mexico
Energy, Minerals and Natural Resources Department

Susana Martinez
Governor

David Martin
Cabinet Secretary

Tony Delfin
Deputy Cabinet Secretary

David R. Catanach, Division Director
Oil Conservation Division



July 5, 2016

Certified Mail Return Receipt# 7015 0640 0007 1331 3551

Lori Notor
Burlington Resources Oil Gas Co LP
3401 E. 30th Street
Farmington, NM 87402

Re: Well Name San Juan 28 5 Unit 46, UL G Sec 25 Twn 28N Rge 5W,
API # 30-039-07342

Dear Ms. Notor:

The 2016 Bradenhead test on the above well indicates a failure by direct communication. In order to comply with Rule 19.15.16.11, prevent waste and protect fresh water, you are hereby directed to initiate remedial activity before **September 16, 2016**. Initial Surface Casing psi was 0. Initial Intermediate Casing was 136. Initial Production Casing psi was 136. Production casing dropped while intermediate was open.

Gas analysis and wellbore schematic have been received.

Reference: RBDMS MPK1613754688 on future correspondence for this issue.

Notify the Aztec OCD 24 hours before work is initiated.

If you have any questions, please call me at 505-334-6178, ext. 116.

Sincerely yours,

Brandon Powell
Deputy Oil and Gas Inspector
District III - Aztec

CC: Well File
BLM Farmington Field Office