## State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez

Governor

David Martin
Cabinet Secretary

Tony Delfin Deputy Cabinet Secretary David R. Catanach, Division Director Oil Conservation Division



July 5, 2016

## Certified Mail Return Receipt#: 7013 1090 0001 7318 4418

Lori Notor ConocoPhillips Company 3401 E. 30<sup>th</sup> Street Farmington, NM 87402

Re: Well Name Carson SRC #4E, UL K Sec 2 Twn 30N Rge 5W, API # 30-039-30418

Dear Ms. Notor:

The 2016 Bradenhead test on the above well indicates a failure. In order to comply with Rule 19.15.16.11, prevent waste and protect fresh water, you are hereby directed to initiate remedial activity before **September 23, 2016.** Initial Surface Casing psi was 0. Initial Intermediate Casing psi was 119. Initial Production Casing psi was 119. Production Casing dropped while Intermediate Casing was open indicating direct communication.

The Gas analysis and wellbore schematic have not been received.

Reference: RBDMS MPK1617557678 on future correspondence for this issue.

Notify the Aztec OCD 24 hours before work is initiated.

If you have any questions, please call me at 505-334-6178, ext. 116.

Sincerely yours,

Brandon Powell

Deputy Oil and Gas Inspector

Brandon Towell

District III - Aztec

CC: Well File

BLM Farmington Field Office