

## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

BRADENHEAD TEST REPORT (submit 1 copy to above address)	
	HUNTWETON API #30-0 39-27744 Location: Unit_Section_3_Township_29 Range7
Property Name CANON LANGO Well No. 3	Location: UnitSection_3_Township_24 Range_7
Well Status(Shut-In or Producing) Initial PSI: Tubing 3_ Intermediate MM Casing 70_ Bradenhead 0_	
OPEN BRADENHEAD AND INTERMEDIATE TO	O ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH
PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
TIME 90	Steady Flow
10 min	Surges
15 min / / 90	Down to Nothing
20 min	Nothing X
25 min	Gas
30 min	Gas & Water
	Water
If bradenhead flowed water, check all of the descriptions that apply below:	
CLEAR FRESH SALTY SULFUR BLACK	
5 MINUTE SHUT-IN PRESSURE BRADENHEAD O INTERMEDIATE	
REMARKS: OPENED THE BOLADEN HEAD AND NOTHING CAME OLT.	
OPENDO THEODOLING TH	And Former Chine ODI.
the new	
By A w	OIL CONS. DIV DIST. 3
(Position)	JUL 07 2016
E-mail address	