District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III
1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe NIM 87505

OIL CONS. DIV DIST. 3

Form C-141 Revised August 8, 2011

JUL 22 2016

Submit 1 Copy to appropriate District Office to accordance with 19.15.29 NMAC.

				30	шна г	c, INIVI o/	003						
			Rel	ease Notific	catio	n and Co	orrective A	ction					
						OPERA'	×	Initi	al Report	$\boxtimes$	Final Report		
Name of Company ConocoPhillips Company						Contact Crystal Walker							
						Telephone No.(505) 326-9837							
		uan 32 Fede					e: Gas Well						
Surface Owner BLM Mineral Owner B							BLM (SF-079329) API No.30-045-31001						
						N OF RE							
Unit Letter	Section	Township	Range	Feet from the		South Line	Fact/Was	East/West Line County					
G	13	32N	9W	2600	The state of the s	North	Feet from the 1880	The state of the s	East		San Juan		
				NAT		OF REL							
Type of Release Fuel Gas Resulting in Fire										Recovered		ubic feet	
Source of Release Regulator inside Transfer Pump						Date and Hour of Occurrence June 9, 2016 at 11:27AM			Date and Hour of Discovery June 9, 2016 at 11:27AM				
Was Immediate Notice Given?  ☐ Yes ☐ Not Required						If YES, To Whom?  Brandon Powell  * Notification was made on June 13, 2016 to OCD that an incident had occurred and an investigation underway. At that time, ConocoPhillips did not believe this incident was subject to reporting requirements.							
By Whom? Lori Notor						Date and Hour June 13, 2016							
Was a Watercourse Reached?  ☐ Yes ☑ No						If YES, Volume Impacting the Watercourse.							
If a Watercook	urse was Im	pacted, Descr	ibe Fully.	*									
Personnel an allowed appr Two personn immediately.	rived on loca roximately 9 nel were inju	cubic feet of ured, and the f	leshoot a t fuel gas to ire self-ex	ransfer pump eng o be released. The tinguished. No pr	e engine	e was cranked	over, and the fue	l gas ignited	d inside	the transfer	pump	building.	
		and Cleanup A -up was requi		cen.*									
regulations a public health should their or the enviro	Il operators or the envir operations h nment. In a	are required to ronment. The lave failed to	o report as acceptant adequately OCD accep	e is true and comp nd/or file certain r ce of a C-141 report investigate and r otance of a C-141	elease nort by the emediate	notifications a ne NMOCD m te contaminati	nd perform correct arked as "Final Ricon that pose a thr	ctive actions teport" does reat to groun	for rel not rel nd water	eases which ieve the ope r, surface wa	may er rator of ater, hu	ndanger f liability man health	
Signature:	30			lku		OIL CONSERVATION DIVISION							
Printed Name: Crystal Walker							Approved by Environmental Specialist:						
Title: Regulatory Coordinator							Approval Date: 106/2016 Expiration Date:						

Conditions of Approval:

20 16 Phone: (505) 326-9837 \* Attach Additional Sheets If Necessary

E-mail Address: crystal.walker@conocophillips.com



Attached