

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company Burlington Resources, a Wholly Owned Subsidiary of ConocoPhillips Company	Contact Lisa Hunter
Address 3401 East 30th St, Farmington, NM	Telephone No. (505) 258-1607
Facility Name: San Juan 29-7 Unit 52A	Facility Type: Gas Well

Surface Owner Federal	Mineral Owner Federal	API No. 3003923944
------------------------------	------------------------------	---------------------------

LOCATION OF RELEASE

Unit Letter J	Section 07	Township 29N	Range 07W	Feet from the 1790	North/South Line South	Feet from the 1450	East/West Line East	County Rio Arriba
-------------------------	----------------------	------------------------	---------------------	------------------------------	----------------------------------	------------------------------	-------------------------------	-----------------------------

Latitude **36.73805** Longitude **-107.60763**

NATURE OF RELEASE

Type of Release Natural Gas	Volume of Release 212 Mcf	Volume Recovered 0
Source of Release Casing Valve on Well Head	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 07/18/16 @ 2:00 PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A



Describe Cause of Problem and Remedial Action Taken.*

During routine site visit/inspection, MSO discovered a Casing Valve on the Well Head leaking and releasing to atmosphere. Valve was turned off and repaired.

Describe Area Affected and Cleanup Action Taken.*

No soil contamination. No further remediation required.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Lisa Hunter		Approved by Environmental Specialist 	
Title: Field Environmental Specialist		Approval Date: 8/2/2016	Expiration Date:
E-mail Address: Lisa.Hunter@cop.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: July 19, 2016 Phone: (505) 258-1607		NUE 1621530644	

* Attach Additional Sheets If Necessary

①