



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

AUG 24 2016

Date of Test 7/11/16 Operator Reddy Production API #30-0 39-24/43
Property Name Chacon Sil. Ap. D# Well No. 11 Location: Unit 6 Section 14 Township 23 Range 3
Well Status (Shut-In or Producing) Initial PSI: Tubing 2 Intermediate 0 Casing 2 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
5 min	0	0	3	0	3
10 min	0	0	3	0	3
15 min	0	0	3	0	3
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing / Vacuum	Vacuum
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

Out side Bradenhead, Inside intermediate, BH
Vacuum Puff When opened Pictures have been taken.
Nothing when opened after 5 min. shut in. Inter vacuum broke down

By Jim Lip

Witness Monica Kuehling 10 sec.

(Position)

E-mail address _____

Nothing on Inter. after
5 min. shut in.