Submitted in lieu of Form 3160-5 (June 1990)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

## SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT" - for such proposals.

RECEIVED

FORM APPROVED

Budget Bureau No. 1004-0135

Expires: March 31, 1993

SEP 0 2 2016

Farmington Field Office Bureau of Land Management

I. Type of Well:		5. Lease Number:
Gas		SF-079947
2. Name of Operator:		6. If Indian, allottee or Tribe Name:
ConocoPhillips		
. Address and Phone No. of Operator:		7. Unit Agreement Name:
P. O. Box 4289, Farmington, NM 87499		8. Well Name and Number:
(505) 326-9700		HELEN JACKSON 2A
. Location of Well, Footage, Sec. T, R, U:		9. API Well No.
FOOTAGE: 940' FSL & 1775' FEL		3004523294
S: 33 T: 029N R: 009W U:	0	10. Field and Pool:
		DK - BASIN::DAKOTA
		MV - BLANCO::MESAVERDE
		11. County and State:
		SAN JUAN, NM
Abandonment	Altering Casing Other- Re-Delivery	Water Shut Off Conversion to Injection
This well was re-delivered on 8/22/2016 and p		trained hydrocarbons. TO EQUIPMENT ISSUE / RETURNED TO PRODUCTION
This well was re-delivered on 8/22/2016 and p		
This well was re-delivered on 8/22/2016 and p		
This well was re-delivered on 8/22/2016 and p		TO EQUIPMENT ISSUE / RETURNED TO PRODUCTION  OIL CONS. DIV DIST. 3
This well was re-delivered on 8/22/2016 and p  Notes: REDELIVERED / SHUT IN FOR M  TP: 329 CP: 317	ORE THAN 90 DAYS DUE	TO EQUIPMENT ISSUE / RETURNED TO PRODUCTION
This well was re-delivered on 8/22/2016 and p  Notes: REDELIVERED / SHUT IN FOR M  TP: 329 CP: 317  Meter No.: 90978	ORE THAN 90 DAYS DUE	TO EQUIPMENT ISSUE / RETURNED TO PRODUCTION  OIL CONS. DIV DIST. 3
This well was re-delivered on 8/22/2016 and p  Notes: REDELIVERED / SHUT IN FOR M  TP: 329 CP: 317	ORE THAN 90 DAYS DUE	TO EQUIPMENT ISSUE / RETURNED TO PRODUCTION  OIL CONS. DIV DIST. 3
This well was re-delivered on 8/22/2016 and p  Notes: REDELIVERED / SHUT IN FOR M  TP: 329 CP: 317  Meter No.: 90978	ORE THAN 90 DAYS DUE	TO EQUIPMENT ISSUE / RETURNED TO PRODUCTION  OIL CONS. DIV DIST. 3
This well was re-delivered on 8/22/2016 and p Notes: REDELIVERED / SHUT IN FOR M  TP: 329 CP: 317  Meter No.: 90978  Gas Co.: ENT  Proj Type.: RECOMPLETE	ORE THAN 90 DAYS DUE	OIL CONS. DIV DIST. 3 SEP 16 2016
Notes: REDELIVERED / SHUT IN FOR M  TP: 329 CP: 317  Meter No.: 90978  Gas Co.: ENT  Proj Type.: RECOMPLETE  4. I Hereby certify that the foregoing is true and Bollie Busse	ORE THAN 90 DAYS DUE  Initial MCF: 235  correct.	OIL CONS. DIV DIST. 3 SEP 16 2016  ACCEPTED FOR RECORD
This well was re-delivered on 8/22/2016 and p  Notes: REDELIVERED / SHUT IN FOR M  TP: 329 CP: 317  Meter No.: 90978  Gas Co.: ENT  Proj Type.: RECOMPLETE  4. I Hereby certify that the foregoing is true and signed	ORE THAN 90 DAYS DUE  Initial MCF: 235  correct.	OIL CONS. DIV DIST. 3 SEP 16 2016