Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

5.	Lease	Serial No.
	NMS	F079160

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

Do not use thi abandoned we	is form for proposals to drill II. Use form 3160-3 (APD) fo		6. If Indian, Allottee or Tribe Name					
SUBMIT IN TRI	PLICATE - Other instruction	erse side.	7. If Unit or CA/Agreement, Name and/o 892000916D					
1. Type of Well				8. Well Name and No.	2			
☐ Oil Well ☐ Gas Well ☐ Oth		RINCON UNIT 212						
Name of Operator CHEVRON MIDCONTINENT,	Contact: APR		-IL		9. API Well No. 30-039-21716-0	0-S1		
3a. Address 332 ROAD 3100 AZTEC, NM 87410		Phone No : 505.33		(include area code) 10. Field and Pool, or Exploratory OTERO CHACRA				
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description)				11. County or Parish,	and State		
Sec 12 T26N R7W SESE 100 36.494949 N Lat, 107.520920					RIO ARRIBA CO	OUNTY, NM		
12. CHECK APPI	ROPRIATE BOX(ES) TO IN	DICATE	NATURE OF	NOTICE, R	EPORT, OR OTHE	R DATA		
TYPE OF SUBMISSION		a .	TYPE O	F ACTION		Tipo si		
- National Change	☐ Acidize	□ Deepen □ Pro			tion (Start/Resume)	☐ Water Shut-Of	f	
☐ Notice of Intent	☐ Alter Casing	☐ Frac	ture Treat	☐ Reclan	nation	☐ Well Integrity		
Subsequent Report	☐ Casing Repair	□ New	Construction	☐ Recom	plete	Other		
☐ Final Abandonment Notice	☐ Change Plans	□ Plug	and Abandon	☐ Tempo	rarily Abandon			
66	☐ Convert to Injection	☐ Plug	Back	☐ Water	Disposal			
testing has been completed. Final At determined that the site is ready for final At determined that the site is ready for final CHEVRON MIDCONTINENT 4/25/2016 RU Cutters Wireline RIH & Set CIBP #1 @ 3604' Run CBL - TOC @ 262' Mix and dumped 0.6 bbl ceme RIH & Set CIBP #2 @ 2798' Mix and dumped 0.6 bbl ceme RIH & Set CIBP #3 @ 2564' R/D Wireline, SIWFN 4/26/2016 RU Cutters Wireline	inal inspection.) HAS COMPLETED PART TW ent (100') on top of CIBP #1	0 OF TH	The second process of	PLUG AND		F THIS WELL.		
14. I hereby certify that the foregoing is Con Name (Printed/Typed) APRIL EF	For CHEVRON MIDCO mmitted to AFMSS for processi	ONTINEN	r, LP, sent to the CK SAVAGE on 0	Farmington	6CXM0251SE)			
Signature (Electronic S	Submission)		Date 09/02/2	016				
	THIS SPACE FOR F	EDERA	L OR STATE	OFFICE U	SE			
Approved By ACCEPT	ED		JACK SAVAGE TitlePETROLEUM ENGINEER Date 09/0				2016	
Conditions of approval, if any, are attache certify that the applicant holds legal or equ which would entitle the applicant to condu	itable title to those rights in the subje		Office Farmington					
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent				willfully to m	ake to any department or	agency of the United		

Additional data for EC transaction #349990 that would not fit on the form

32. Additional remarks, continued

Run CBL - CBL uploaded to NMOCD and sent to BLM. Mix and dumped 0.6 bbl cement (100') on top of CIBP #3 RIH & Set CIBP #4 @ 2246' Mix and dumped 0.6 bbl cement (100') on top of CIBP #4 RIH & Set CIBP #5 @ 2016'
Mix and dumped 0.6 bbl cement (100') on top of CIBP #5
RIH & Set CIBP #6 @ 946' Mix and dumped 0.6 bbl cement (100') on top of CIBP #6 Rig down. 7/27/2016

MIRU.Check well pressure: 2-7/8": Opsi, 8-5/8" Opsi. Attempt to fill 2-7/8' - standing full. Filled 8-5/8" w 20bbls fresh water. No circ or comm w 2-7/8".

Remove riser and MV - threads on 2-7/8" below MV are not 2-7/8" EUE. Looks like 2" line pipe thread. Re-install MV and riser.

R/U wireline. RIH w/ 2-1/16" GR, tag @789'. POOH, arm gun and RIH w/ 2.01" jet cutter. Correlate to collars and fire cutter at 237'. POOH, R/D wireline.

Remove MV and riser. Remove top union of 8-5/8"Larkin WH connection. While attempting to unscrew top union, it was noticed entire WH was rotating in ground. Re-install MV and riser, pick up. Pulled to 10,000lbs trying to free 2-7/8" from 8-5/8" Larkin head w no movement. circ down tubing w/ 5bbls fresh water, circ up 8-5/8". SWIFN.

Check well pressure: 2-7/8" Opsi, 8-5/8" Opsi. Removed MV, installed flange and WH hanger jack. Pressured up. recorded a max force of 30,000lbs before slip hanger came free. R/D hanger jack. Pull 2-7/8" casing, recovered 10ft pup, 6jts, 1 cut piece. Tallied 234'. RIH w/ 7jts 2-7/8" workstring to 230'. Install slip hanger, land in Larkin head. R/U cementers. Press test lines to 2000psi. Fill hole w/ 7bbls fresh water - establish circulation.

Pump neat G cement @15.8ppg 1BPM while maintaining returns. Circulation declined, lost circulation after 10bbls cement pumped. Continue pumping cement, getting returns outside the 8-5/8" surface casing. Regained returns to tank after 24bbls pumped, saw cement in tank returns, pumped added 3bbls to tank. Total 27bbls cement slurry pumped. Shut down. Topped off cement down 8-5/8" w/ added 1bbl cement. Cement top staying at surface.

Job total 28bbls cement (125sx). Rig down, prepare to move.

7/29/16

Well pressure: 0psi. Excavate around WH, expose concrete support 3ft below surface. Consult w BLM rep (John Hagstrom), make WH cut above concrete support 1ft below ground level.

TOC inside 8-5/8" measured 8 inches below cut (20" below ground level). Top w 1sack concrete. Weld on dry hole marker, back fill around WH.



Wellbore Schematic

Nei Name Rincon 212	Rincon Unit	Field Name Susiness Unit Rincon Mid-Continent								
	Land - Original Hole, 6/4/2015 7:21:45 AM	Job Details								
MD	Markey and and the Control		Start Date				nt End Date			
H)	Vertical schematic (actual)	Abandon				4/25/2			4/26/2016	
		Abandon	Maria II			7/27/2	U16		7/29/2016	
***	O BIESA	Casing Strings		CTAA!	Ny ent		SELECT OF	1274 20		1 0-0
	63 1 1 1 1 1	Cog Des	1990	00 (Irr)	Witten	(1010)	G	rade	Top Thread	Set Dept (MD) (ND)
	Casing Joint, 15-145, 130.00; 1-1, 8	Surface		8 5/8		24.00	K-55			To the same of
*480	Figal Short 145-145, 1.00, 1-2, 8 58,	Production Cas	ing	27/8		6.40	J-55			3,7
****	8.097	Perforations		1		Pale				
		Unit Compa			Shot Dens	Entered	Shot			
2344				3,676.0	(sincts/ft)	Total		Chann	United Zone	OTTO TA
set+			3,654.0	3,720.0	1.0		-	The second second	Original Hole	
- 8			Delay of the last	3,756.0	1.0	_		THE RESERVE TO SHARE THE PARTY OF THE PARTY	s, Original Hole s, Original Hole	
HEED TO THE SECOND		SOURCE STATE OF THE PARTY OF	3,740.0	3,750.0	1.0		17	Chacra	, Original noie	
HAZ ST		Other Strings	Puli Date	Set De	HTOR) rits		The Control	No.	Com	
- 8		BURNING S		010 F388 H	Managan					
Pas S		Other In Hole	his hani	This is a		to Aleg				RSDV BY
0181	Casing Joint 237-3,787; 3,550.00; 2- 1; 2,7/8; 2,500	Des	Top (NOT	H) (BOTH		n Date	-	al Date	Co	70
- 1	1,277,2000	Fill (Sand / Mud			0 7/29				Ų0	
drea S		Debris)								
1960		Bridge Plug	948.	.0 948	.0 4/26	2016		TO D		
- 3		(permanent)	2015	0 0 0 0	0.000	2004				
10081		Bridge Plug (permanent)	2,016.	.0 2.018	4/26	2016	100			
1561		Bridge Plug	2.246.	0 2 248	.0 4/26	2016				
- 8		(permanent)				Day of				
initia (E)		Bridge Plug	2,564	0 2,566	0 4/26	2016	70%			
IMAG S	A STATE OF THE STA	(permanent)								
3444		Bridge Plug (permanent)	2,798	.0 2,800	1.0 4/25	2016				
-		Bridge Plug	3,604	0 3.606	0 4/25	2016				
446.2		(permanent)	5,004			2010				
796.0										
-										
797.0										
7664										
(SCE)										
40c0										
1										
4062										
Schill										
	Cased Hole: 3,554-3,576: 4/25/2016									
8 44	0001 1000									
17158	Cased Hole, 3,714-3,720, 4/25/2016									
7001	100 AND 100 AN									
7402	Cased Hole: 3,740-3,756; 425/2016									
1928	State Control of the									
-										
777.4										
001										
	Float Shoe, 3,787-3,789, 2.00, 2-2, 2 76; 2.500									
		- 11								
7960		11								
7660										

HALLIBURTON

iCem[®] Service

CHEVRON - MID-CONTINENT EBIZ

For: Gabe Collins
Date: Thursday, July 28, 2016

RINCON 212

RINCON-212 Case 1 Job Date: Thursday, July 28, 2016

Sincerely, John Keane

HALLIBURTON

Customer: CHEVRON - MID-CONTINENT EBIZ

Job: 903451650

Case: Case 1

1.0 Real-Time Job Summary

Туре	Seq	Activity	Graph Label	Date	Time	Source	PS Pump	PS Pump	DH	Pump Stg	Recirc	Comments
туре	No.	Activity	Graph Caser	Date	Time	Source	Press (psi)	Rate (bbl/min)	Density (ppg)	Tot (bbl)	Density (ppg)	Commens
Event	1	Call Out	Call Out	7/28/2016	04:00:00	USER						REQUESTED ON LOCATION TIME 09:00
Event	2	Pre-Convoy Safety Meeting	Pre-Convoy Safety Meeting	7/28/2016	06:00:00	USER						WITH HES, 1 F-450, 1 RT CEMENTING UNIT, 1 660 BULK TRUCK
Event	3	Arrive At Loc	Arrive At Loc	7/28/2016	08:11:10	USER						RIG RUNNING IN HOLE WITH TUBING, UPON HES ARRIVAL
Event	4	Assessment Of Location Safety Meeting	Assessment Of Location Safety Meeting	7/28/2016	08:30:00	USER				F. = 51		WTH HES, DISCUSSED JOB PROCEDURE WITH COMPANY REP, TESTED WATER (CHLOR 0, PH 7.5, TEMP 81 DEG), SDS WAS OFFERED FOR ALL HES MATERIALSA
Event	5	Pre-Rig Up Safety Meeting	Pre-Rig Up Safety Meeting	7/28/2016	09:30:00	USER						WITH HES,
Event	6	Rig-Up Equipment	Rig-Up Equipment	7/28/2016	09:40:00	USER						1 LINE RAN TO THE FLOOR, 1 LINE RAN FROM BACKSIDE TO PIT
Event	7	Pre-Job Safety Meeting	Pre-Job Safety Meeting	7/28/2016	10:15:00	USER						WITH HES, CHEVRON, AND ALLIANCE ENERGY
Event	8	Start Job	Start Job	7/28/2016	10:28:38	COM4						TB 230 FT 2.875 IN 6.5 LB/FT J-55, CSG 140 FT 8.625 IN 40 LB/FT J-55, HOLE 7.875 IN BELOW SURFACE CASING, WELL FLUID 8.33 LB/GAL FRESH WATER
Event	9	Prime Pumps	Fill Lines	7/28/2016	10:29:24	USER	12.00	1.50	8.33	1.5		FRESH WATER

iCem" Service

(v. 4.2.393) Created: Thursday, July 28, 2016

HALLIBURTON

Customer: CHEVRON - MID-CONTINENT EBIZ

Job: 903451650 Case: Case 1

Event	10	Test Lines	Test Lines	7/28/2016	10:32:54	USER	2685.00	0.00	8.33	1.5	LOW TEST AT 2000 PSI, HIGH TEST AT 2685 PSI, PRESSURE HOLDING
Event	11	Pump Spacer	Pump Spacer	7/28/2016	10:36:18	USER	9.00	1.10	8.33	0.1	FRESH WATER, RETURNS AT 7 BBL AWAY
Event	12	Shutdown	Shutdown	7/28/2016	10:40:22	USER	16.00	0.80	8.29	7.0	SHUTDOWN
Event	13	Pump Cement	Pump Cement	7/28/2016	10:50:38	USER	9.00	1.10	15.80	23.0	MIXED AT 15.8 LB/GAL, 125 SKS, 1.16 FT3/SK, 5.13 GAL/SK, DENSITY VERIFIED USING PRESSURIZED MUD SCALES
Event	14	Shutdown	Shutdown	7/28/2016	11:20:34	USER	35.00	0.00	16.14	23.0	CEMENT CIRCULATED TO SURFACE, SHUTDOWN
Event	15	Comment	Comment	7/28/2016	11:25:33	USER	12.00	0.00	15.82	23.0	RIG PULLED TUBING OUT OF THE HOLE
Event	16	Pump Cement	Pump Cement	7/28/2016	11:41:17	USER	15.00	0.50	15.80	3.8	MIXED AT 15.8 LB/GAL, 1.16 FT3/SK, 5.13 GAL/SK, DENSITY VERIFIED USING PRESSURIZED MUD SCALES, 2% CALCIUM CHLORIDE ADDED TO CEMENT
Event	17	End Job	End Job	7/28/2016	11:42:29	USER	38.00	1.50	15.80	26.8	GOOD CIRCULATION, PIPE WAS STATIC, RIG USED 50 LB CALCIUM CHLORIDE, 100 LB SUGAR, NO ADD HOURS CHARGED
Event	18	Pre-Rig Down Safety Meeting	Pre-Rig Down Safety Meeting	7/28/2016	12:00:00	USER				2	WITH HES
Event	19	Rig-Down Equipment	Rig-Down Equipment	7/28/2016	12:15:00	USER		- I			
Event	20	Crew Leave Location	Crew Leave Location	7/28/2016	13:00:00	USER			an list		THANKS FOR USING HALLIBURTON, JOHN KEANE AND CREW
Event	21	Pre-Convoy Safety Meeting	Pre-Convoy Safety Meeting	7/28/2016	13:20:00	USER					WITH HES


iCem® Service

(v. 4.2.393) Created: Thursday, July 28, 2016


Job: 903451650 Case: Case 1

2.0 Custom Graphs

2.1 Custom Graph



Chevron - Rincon 212 - PTA



PS Pump Press (psi)	PS Pump Rate (bbl/min) DH Density (ppg) Pump	o Stg Tot (bbl) Recirc Density (ppg) Water Stg Tot (bbl)
① Call Out n/a;n/a;n/a; n/a	® Start Job 14;11;4.62;	© Comment 12,0,15.82; 6 * 11 = 33.21
2 Pre-Convoy Safety Meeting Na.n/a;n/a; n/a	Fill Lines 12:15.8.32;	Pump Cement 15,0.5,15.54; 8.4 33.36
3 Arrive At Loc n/a,n/a,n/a; n/a	@ Test Lines 2685;0;8.35; 0 0	@ End Job 38;1.5;15.34; 33.36
Assessment Of Location Safety Meeting n/a.n/a.n/a;	n/a @ Pump Spacer 9;1.1;8.26; 2.21	Pre-Rig Down Safety Meeting 8,0;15.44; 33.36
⑤ Pre-Rig Up Safety Meeting n/a,n/a,n/a,n/a,n/a	② Shutdown 16;0.8;8.29;4 2.21	Rig-Down Equipment 55, 1.7;13.89; 37.98
6 Rig-Up Equipment n/a,n/a;n/a;n/a;n/a	@ Pump Cement 9;1.1;15.39; 12.55	20 Crew Leave Location n/a,n/a;n/a;n/a
The Pre-Job Safety Meeting 12,0,8.67;4 2 37	Shutdown 35,0;16.14;38 3, □ ■ 33.21	21 Pre-Convoy Safety Meeting n/a,n/a,n/a, n/a
▼ HALLIBURTON iCem® Service	and the same of th	Created: 2016-07-28 05:33:37, Version: 4.2.393 Edit

Customer: CHEVRON - MID-CONTINENT EBIZ

Representative: GABE COLLINS

Job Date: 7/28/2016 9:56:47 AM Sales Order #: 903451650

Well: RINCON 212

RT 2: JOHN KEANE / JAKE AYERS