



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emurad.state.nm.us/ocd/District III3/district.htm](http://emurad.state.nm.us/ocd/District%20III3/district.htm)

OIL CONS. DIV DIST. 3

OCT 11 2016

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10/11/2016 Operator Burlington API #30-0 39-07360

Property Name San Juan 28.5 Unit Well No. 22 Location: Unit M Section 21 Township 28 Range 5

Well Status (Shut-In or Producing) Initial PSI: Tubing 134 Intermediate 35 Casing 136 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead	INTERM	Int	Csg
		Int	Csg	Int	Csg
TIME					
5 min	0	35	138	1	139
10 min	0	35	138	TSTM	139
15 min	0	35	139	TSTM	139
20 min				TSTM	139
25 min				TSTM	139
30 min				0	140

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	X
Down to Nothing	X
Nothing	X
Gas	X
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

BH + Int through 1" valves, Nothing on BH, Int hard blow for 3min, moderate blow for 5min 30sec, down to light breath @ 6min w/ surges

By Kyle D Smith

Witness Janet D Kelly

(Position)

E-mail address _____