

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Jun 19, 2008

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.

30-039-26200

5. Indicate Type of Lease

STATE ☐ FEE ☒

6. State Oil & Gas Lease No.
FEE

7. Lease Name or Unit Agreement Name
San Juan 30-5 Unit

8. Well Number 220R

9. OGRID Number
217817

10. Pool name or Wildcat
Basin Fruitland Coal

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☒ Other

2. Name of Operator
ConocoPhillips Company

3. Address of Operator
P.O. Box 4289, Farmington, NM 87499-4289

4. Well Location

Unit Letter N : 791 feet from the South line and 1980 feet from the West line
Section 8 Township 30N Range 5W NMPM Rio Arriba County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
6259' GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

☒ Location is ready for OCD inspection after P&A

- ☒ All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.
- ☒ Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.
- ☒ A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It show the

**OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR
PERMANENTLY STAMPED ON THE MARKERS SURFACE.**

- ☒ The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.
- ☒ Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.
- ☒ If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.
- ☒ All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)
- ☒ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.

When all work has been completed, return this form to the appropriate District office to schedule an inspection.

SIGNATURE Dollie L. Busse TITLE Regulatory Technician DATE 10/16/2016

Type or print name Dollie L. Busse E-mail address: dollie.l.busse@conocophillips.com PHONE: 505-324-6104

For State Use Only

APPROVED BY: _____
Conditions of Approval (if any): _____

DENIED

Several pieces of liner across East side of location along with other debris.

BY: Jonathan Kelly
DATE: 10/11/2016 (505) 334-6178 Ext. 122

OCT 11 2016

Reclamation Form:

Date: 10-5-16

Well Name: Sp. 30-5 Unit 220R

Footages: 791' ESL / 1979' FWL Unit Letter: N

Section: 8, T-30 -N, R-5 -W, County: R. B. R. L. State: NM.

Reclamation Contractor: Kuytore

Reclamation Start Date: 10-3-16

Reclamation Complete Date: 10-4-16

Road Completion Date: 10-4-16

Seeding Date: 10-5-16

****PIT MARKER STATUS (When Required):** Picture of Marker set needed

MARKER PLACED: _____ (DATE)

LATITUDE: N/A

LONGITUDE: _____

Pit Manifold removed _____ (DATE)

Construction Inspector: Stan M. Mabrian Date: 10-5-16

Inspector Signature: [Signature]

Office Use Only: Subtask DSM Folder _____ Pictures _____

RCC Reclamation Completion Checklist

*Complete each segment that applies and mark N/A for others

Location: <u>San Juan 30.5 - 220R</u>	New Facility? Yes <input type="radio"/> No <input checked="" type="radio"/>	Network/RFE/WO#: <u>10376223</u>	Date: <u>10-5-14</u>
BLM Contact: <u>FEF</u>	Operations/First Delivery Contact: <u>N/A</u>		

Notes: Initial at least one box for each item listed. (All boxes must be completed before completion)

This RCC form is applicable for Reclamations, P&A Reclamations and Landfarm Reclamations.

Complete the applicable segment and mark N/A for the others

RCC must be completed before planning order can be marked complete and closed in the system.

Comments:	Completed	Incomplete	N/A	Comments:	Completed	Incomplete	N/A	Comments:	Completed	Incomplete	N/A
Interim Reclamation	Initial			P&A Reclamation	Initial			Landfarm Reclamation	Initial		
Has APD been reviewed prior to work beginning				Has 72 hour notice been issued to the proper people	<input checked="" type="checkbox"/>			Has closure work order been received from SAP			
Has 72 hour notice been issued to the proper people				Has all equipment and piping been removed	<input checked="" type="checkbox"/>			Has BLM been notified of Intent to close Landfarm			
Have pit sample results been received				Have all anchors been removed	<input checked="" type="checkbox"/>			Has onsite meeting with BLM taken place			
Has water been removed from pit				Does contouring meet Gold Book standards	<input checked="" type="checkbox"/>			Have berms and material been properly respread			
Is there adequate freeboard to establish 4' of cover				Has top soil been spread evenly	<input checked="" type="checkbox"/>			Has landfarm been properly disc and seeded			
Does contouring meet Gold Book standards				Has location been properly ripped	<input checked="" type="checkbox"/>			Has proper seed mix been used			
Has top soil been spread evenly				Has all road stipulations been met	<input checked="" type="checkbox"/>			Is all trash and debris been removed from location			
Has location been properly disc				Has CMP's been removed	<input checked="" type="checkbox"/>			Has landfarm reclamation form been turned in			
Has location been seeded with proper seed mix				Has pit marker been removed			<input checked="" type="checkbox"/>	Notes:			
Has back slopes been properly seeded				Has location been properly disc	<input checked="" type="checkbox"/>						
Have wellhead guards and jersey barriers been removed				Has location been seeded with proper seed mix	<input checked="" type="checkbox"/>						
Has trash and debris been removed from location				Has access road been properly seeded	<input checked="" type="checkbox"/>						
Have reclamation and pit marker photos been taken				Has trash and debris been removed from location	<input checked="" type="checkbox"/>						
Dig and Haul				Has final reclamation photos been taken	<input checked="" type="checkbox"/>						
Has certificate of waste been issued to landfarm				Has P&A reclamation form been turned in	<input checked="" type="checkbox"/>						
Have all pit contents including liner been removed				Notes:							
Has sample after content removal been taken											
Notes:											
Interim Reclamation Complete				P & A Reclamation Complete				P & A Reclamation Complete			
Signature: <u>[Signature]</u>				Signature: <u>[Signature]</u>				Signature: <u>[Signature]</u>			
Date: <u>10-5-14</u>				Date: <u>10-5-14</u>				Date: <u>10-5-14</u>			



