



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrdd.state.nm.us/ocd/District III3district.htm](http://emrdd.state.nm.us/ocd/District%20III3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 18 OCT 2016 Operator WPX API #30-0 39-29502

Property Name ROSA UNIT Well No. 389A Location: Unit C Section 7 Township 31 Range 4

Well Status(Shut-In or Producing) Initial PSI: Tubing 3.5 Intermediate N/A Casing 3.5 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead				
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	N/A	3.6		
10 min	0	N/A	3.6		
15 min	0	N/A	3.6		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	X	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

OPEN ED THE BRADENHEAD AND NOTHING CAME OUT.

By Darren Rowley
Foreman
(Position)

Witness John D. [Signature]

E-mail address darren.rowley@wpxenergy.com