

State of New Mexico
Energy, Minerals and Natural Resources Department

Susana Martinez
Governor

Tony Delfin
Acting Cabinet Secretary

David R. Catanach, Division Director
Oil Conservation Division



October 24, 2016

ConocoPhillips Company
Ms. Lori Notor
3401 E 30th Street
Farmington NM, 87402

Re: Bradenhead Test Failure

Well: Jicarilla 153 #3, UL D, Sec 26, Tw 26N, Rge 5W, API # 30-039-06333

Certified Mail Return Receipt: 7015 0640 0007 1331 3667

Dear Ms. Notor:

The 2016 Bradenhead test on the above well indicates a failure. To comply with Rule 19.15.16.11, prevent waste and protect fresh water, you are hereby directed to submit a plan of action before **November 20, 2016**, and initiate remedial activity before **January 20, 2017**. Initial Surface Casing psi was 49. Initial Production Casing psi was 104. Five-minute shut in pressure was 17.

The Gas analysis was received July 29, 2016. The gas analysis shows the bradenhead gas and production casing gas have the same composition.

Reference: RBDMS MPK1628740252 on future correspondence for this issue.

Notify the Aztec OCD 24 hours before work is initiated.

If you have any questions, please call me at 505-334-6178, ext. 116.

Sincerely yours,

Brandon Powell
Deputy Oil and Gas Inspector
District III - Aztec

CC: Well File