

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.mn.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test_	5-21-	2016 Operato	Or Black Hills API#3	30-0 39 - 24301
Property Nan	ne 464	Well No	7 Location: Unit D Section 2	79 Township W Range 3W
Well Status(Shut-In or Producing) Initial PSI: Tubing 35 Intermediate 4/2 Casing 2 Bradenhead 0				
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH				
PRESSURE		FLOW CHA	RACTERISTICS	
Testing	Bradenhead	INTERM	BRADENHEAD	INTERMEDIATE
TIME	Int Csg	Int Csg		
5 min	2		Steady Flow	
10 min 0	2		Surges	
15 min 0	2		Down to Nothing	
20 min			Nothing	/-
25 min			Gas	
30 min			Gas & Water	
30 mm				OIL CONS. DIV DIST. 3
WaterDIST.				
If bradenhead flowed water, check all of the descriptions that apply below:				
CLEAR FRESH SALTY SULFUR BLACK				
5 MINUTE SHUT-IN PRESSURE BRADENHEAD O INTERMEDIATE MA				
REMARKS: BRADIEN head has 2" VALVE. Blew down.				
I SEC. NO VAPORS				
7 300 1 100 17100 13				
вуДел	R. Bake	<i>l</i>	Witness	_
(Position)				
E-mail address				