

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd//District III/3distric.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test May 19, 2016 Operator Blackhills Gas Resources API #30-0 39 - 26059							
Property Name Jicarila 462 - 26 Well No. 11 Location: Unit 1 Section 26 Township 30N Range 3W							
Well Status(Shut-In or Producing) Initial PSI: Tubing 9 Intermediate 4/2 Casing 9 Bradenhead 8							
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH							
Testing BH					FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE		
TIME 5 min	N/A	9	NA		Steady Flow	N/ /	
10 min 9	Ī	9	1		Surges	17/A	
15 min Ø	11	9			Down to Nothing		
20 min	\perp		\perp		Nothing	/	
25 min_					Gas		
30 min	1 /		1		Gas & Water	OII CONS. DIV DIST.	
Water							
If bradenhead flowed water, check all of the descriptions that apply below:							
CLEAR FRESH SALTY SULFURBLACK							
5 MINUTE SHUT-IN PRESSURE BRADENHEAD Ø INTERMEDIATE							
REMARKS: nothing When braden head was opened.							
By Kirt D. Vicenti Witness							
(Position)							
E-mail address							