

NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

S Sunda

BRADENHEAD TEST REPORT (submit 1 copy to above address)	
Date of Test May 27, 2016 Operator Blockhills Gas Resources API #30-0 39-26863	
Property Name_icarila 29-02-8 Well No. 3 Location: Unit B Section 8 Township 29N Range 2W	
Well Status(Shut-In or Producing) Initial PSI: Tubing 23 Intermediate MA Casing 23 Bradenhead D	
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH	
PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
$\frac{\text{TIME}}{5 \min} \mathcal{D} N_{///} 23 N_{//}$	Steady Flow
10 min Ø (23	Surges
15 min 8 23	Down to Nothing
20 min	Nothing
25 min	Gas
30 min	Gas & Water
	Water
If bradenhead flowed water, check all of the descriptions that apply below: OIL CONS. DIV DIST. 3	
CLEAR FRESH SALTY	SULFURBLACKSEP 0 8 2016
5 MINUTE SHUT-IN PRESSURE BRADENHEAD 8 INTERMEDIATE	
REMARKS: Dothing on bradenhead when opened.	
By Kirt D Vicenti Witness Lease operator (Position) E-mail address	