

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR



Initial Report



Final Report

Name of Company	Chevron Midcontinent, L.P.	Contact	Chester O'Nan
Address	332 CR 3100, Aztec, NM 87410	Telephone No.	(505) 333-1901
Facility Name	Rincon Unit # 223	Facility Type	Gas Well
Surface Owner	BLM	Mineral Owner	BLM
		API No.	30-039-22644

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	34	27	7	1620	South	970	East	Rio Arriba

Latitude 36.526236 Longitude -107.557747

NATURE OF RELEASE

Type of Release	Production fluids	Volume of Release	Unknown	Volume Recovered	TBD
Source of Release	Produced water pit tank	Date and Hour of Occurrence		Date and Hour of Discovery	8/19/2016
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	April Pohl		
By Whom?	Thomas Vermersh	Date and Hour	8/19/2016	7:21 AM	
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

OIL CONS. DIV DIST. 3
OCT 19 2016



Describe Cause of Problem and Remedial Action Taken.*

OCD inspector notified Chevron of stains around the pit tank that needed to be cleaned up. Cleanup of the contaminated soil started on 8/25/16. During cleanup of the stain historical contamination was found, action was then taken to continue digging until visual signs of the historical contamination were removed.

Describe Area Affected and Cleanup Action Taken.*

The affected area was inside the secondary containment beneath the pit tank. Contaminated soil was removed and hauled to the Envirotech land farm for remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Chester O'Nan		Approved by Environmental Specialist: 	
Title: Production Team Lead		Approval Date: 12/5/16	Expiration Date:
E-mail Address: cnoc@chevron.com		Conditions of Approval: Sample For	Attached <input type="checkbox"/>
Date: 10/18/2016 Phone: (505) 947-1000		TPH(DRO-GRO-MRO)-BTEX	

* Attach Additional Sheets If Necessary

#INC 1634057425

Q