



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III3district.htm](http://emnr.state.nm.us/ocd/District%20III3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 1/10/2016 2017 Operator Encana API #30-043-21125

Property Name Lybrook I32 2306 Well No. 2H Location: Unit I Section 32 Township 23 Range 6

Well Status (Shut-In or Producing) Initial PSI: Tubing 98 Intermediate NA Casing 124 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
5 min	0		121		
10 min	0		123		
15 min	0		124		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	X
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE NA

REMARKS:

BH through 1/4" needle valve, plunger ran at start of test, no sign of communication

By Arthur Sullivan
Lead
(Position)

Witness Paul D. Kelly

E-mail address Arthur.sullivan@encana.com

OIL CONS. DIV DIST. 3

JAN 10 2017