

Form 3160-5 (August 1999)

Type of Well

Oil Well

#### UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

DEC 27 2016

FORM APPROVED

Budget Bureau No. 1004-0135 Expires: November 30, 2000

Lease Serial No.

Well Name and No.

Lunt 63

Farmington Field Office SUNDRY NOTICES AND REPORTS ON WELLS require an of Land Manager confrincian, Allottee or Tribe Name

Do not use this form for proposals to drill or to re-enter an

abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

Other

Gas Well

7. If Unit or CA/Agreement, Name and/or No.

2.	Name of Operator							9. API Well No.				
	M&G Drilling Company, Inc.								30-045-09773			
3a.	ı. Address			3b. Phone No. (include area code)			10. Field and Pool, or Exploratory Area					
	PO Box 5940, Farmington, NM 87499				(505) 325-6779			Basin Dakota (Prorated Gas)				
4.	Location of Well (Footage, Sec., T., R., M., or Survey Descri			ption)			11. County or Parish, State					
9	985' FNL & 795' FEL, Sec. 7, T30N-R13W						San Juan, New Mexico					
	,											
12.	CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA											
TYPE OF SUBMISSION				TYPE OF ACTION								
1	Notice of Intent		Acidize		☐ Deepen	7	Production (St	art/Resume)		Water Shu	ut-Off	
			Alter Casing		Fracture Treat		Reclamation			Well Integ	grity	
	Subsequent Report	7	Casing Repair		New Construction		Recomplete			Other	Squeeze Job	
	Subsequent Report		Change Plans		Plug and Abandon		Temporarily A	bandon				
	Final Abandonment Notice		Convert to Injection	on	Plug Back		Water Disposa	ıl				_

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, A Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

M&G Drilling Company received verbal approval from Brandon Powell @ NMOCD and Troy Salyers @ BLM on 12/20/16 to perform squeeze job on the subject well. A+ Well Service will MIRU on 12/27/16.

> SEE ATTACHED FOR CONDITIONS OF APPROVAL

States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

OIL CONS. DIV DIST. 3

DEC 3 0 2016

**ACCEPTED FOR RECORD** 

14. I hereby certify that the foregoing is true and correct					
Name (Printed/Typed) David Hinson	Title Field forman				
Signature Dain Hinson	Date 12-26-16				
THIS SPACE FOR FEDERAL OR STATE OFFICE USE					
Approved by AG E/malan:	Title PE	Date 2/28//4			
Conditions of approval, if any, are attached. Approval of this notice does not warrant or					
certify that the applicant holds legal or equitable title to those rights in the subject lease	Office EEO				
which would entitle the applicant to conduct operation thereon.	FIU				
Title 18 U.C.S. Section 1001 and Title 43 U.S.C. Section 1212, makes it a crime for any person k	nowingly and willfully to make any department or agenc	v of the United			

## LUNT 63 – SQUEEZE PROCEDURE 985' FNL & 795' FEL SEC. 7, T30N-13W SAN JUAN COUNTY, NM LEASE NO. NMNM09867A API # 30-045-09773

12/8/2016:	MIRU JC Well Service, NU BOP, TOH tbg looking for HIT.
12/9/2016:	Found split collar on jt #124 and bad threads on jt #123. Remaining tbg looks good. Ran
	scraper in hole to clean csg. Pull tbg and scraper out, RIH tbg and replaced 2 bad jts.
12/13/2016:	Swab well, made 27 runs, recovered 20 bbls H20, lost swab tool in hole.
12/14/2016:	TOH tbg, got swab equip out of tbg. Ran tbg in hole with bull plug on bottom. Press
	test, blew hole in tbg @ 800 psig. Pulled 34 jts, didn't get to hole.
12/15/2016:	Finish pulling tbg, found split jt. bottom of jt #90. Run tbg in 30 stands at a time, press
	test to 1200 psig. Held
12/16/2016:	POH tbg, swabbing H20 to pit.
12/19/2016:	Used Weatherford packer and plug to test csg. Plug guides broke off. Did not use plug.
	Ran packer in, press text backside. Found hole below 2,166'.
12/20/2016:	Called Brandon Powell @ NMOCD and Troy Salyers @ BLM, got verbal approval to
	perform squeeze job. A+ Well Service to perform csg squeeze on 12/27/2016, w-200
	sks cmt.

# **BLM CONDITION OF APPROVAL**

### CASING REPAIR, WORKOVER AND RECOMPLETION OPERATIONS:

- 1. If casing repair operations are needed, obtain prior approval from this office before commencing repairs. If a CBL or other logs are run, provide this office with a copy.
- 2. After any casing repair operations, test cement squeeze to a minimum of 500# for 30 minutes with no more than 10 % pressure fall off in the 30 minute test period. Provide test chart with your subsequent report of operations
- 3. A properly functioning BOP and related equipment must be installed prior to commencing workover, casing repair, and/or recompletion operations.
- 4. Contact this office at (505) 564-7750 prior to conducting any cementing operations

### **SPECIAL STIPULATIONS:**

- 1. Pits will be fenced during work-over operation.
- 2. All disturbance will be kept on existing pad.
- 3. All pits will be pulled and closed immediately upon completion of the recompletion and work-over activities.
- 4. Pits will be lined with an impervious material at least 12 mils thick.