RECEIVED

Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

JAN 0 4 2017

FORM APPROVED OMB No. 1004-0137

Expires: July 31, 2010

	Farmington	Fie	d Gafficerial No.
-			The second secon

Farmington Field (Afficerial No. Bureau of Land Management SF-078103-B										
ALIS	IDRY NOTICES AND REPO	6. If Indian, Allottee or Tribe N	-078103-B							
	e this form for proposals	o. Il fildiali, Allottee of Tilbe N	ame							
	well. Use Form 3160-3 (A	·								
SL	JBMIT IN TRIPLICATE - Other ins	tructions o	n page 2.		7. If Unit of CA/Agreement, Name and/or No.					
1. Type of Well					Huerfano Unit					
Oil Well			8. Well Name and No.							
2. Name of Operator					9. API Well No.	ano Unit 206				
	ton Resources Oil & Gas	Compa	ıy LP		30-045-20626					
3a. Address		3b. Phone	No. (include area co	code) 10. Field and Pool or Exploratory Area						
PO Box 4289, Farmington	on, NM 87499		505) 326-9700)		sin Dakota				
4. Location of Well (Footage, Sec., T., R		ac Tack Do	NA.	11. Country or Parish, State	New Mexico					
Surface Unit J (N	WSE), 1850' FSL & 1750' F	-EL, Sec	. 26, 126N, R9	VV	San Juan ,	New Mexico				
12. CHECK	THE APPROPRIATE BOX(ES)	TO INDI	CATE NATURE	OF NO	TICE, REPORT OR OTHE	R DATA				
TYPE OF SUBMISSION			TYPE (OF AC	CTION					
Notice of Intent	Acidize	Deepe	n	P	roduction (Start/Resume)	Water Shut-Off				
	Alter Casing	Fractu	re Treat	R	Reclamation	Well Integrity				
Subsequent Report	Casing Repair	New (Construction	R	tecomplete	X Other				
	Change Plans	Plug a	nd Abandon	T	emporarily Abandon	FAN				
X Final Abandonment Notice	Convert to Injection	Plug I	ack	V	Vater Disposal					
13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) The subject well was P&A'd on 5/28/2013. Reclamation was completed and the location is now ready for final closure approval. The location was inspected and passed on 12/28/2016 with Bob Switzer. Please remove this well from the Burlington Resources Oil & Gas LP bond.										
				OILC	ONS. DIV DIST. 3 JAN 1 1 2017					
14. I hereby certify that the foregoing is Dol	true and correct. Name (Printed/Type lie L. Busse	Staff Regulatory Technician Title								

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Title

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



Signature

Approved by

RCC Reclamation Completion			Location Name: Huerfano 206	Date: 12/28/16 Revision 1						
AP#: 3004520626				UL-Sec-Twn-Rng: J-26/26/9	Lat/Long: 36.456860/-107.755250					
Surface Owner: BLM			Lease# :	County/State: San Juan /NM						
Pipeline Owner: Enterprise			Twin/Co-Locate Well Name & Operator:							
Onsite: Agency Inspec			Seed Mix:							
Interim Reclamation		Incomplete	NIA	Final Reclamation		Incomplete	Remediation	Completed	Incomplete	NIA
Have pit sample results been approved				3rd party pipeline removed			Facilities stripped	2.1		
Has water been removed from pit				Anchors removed			Certificate of waste issued & approved			
Have pit marker photos been taken				Equipment and piping removed			Depth:			
Has certificate of waste been issued & approved				Power poles removed			Width:			
Have all pit contents been removed				Cathodic protection removed	X		Length:			
Has sample after content removal been taken				Vegetative cages removed			Date of Excavation Start:			
Is location contoured				CMP's removed		×	Date of Excavation End:			
Is there 4' of cover over pit				Non native gravel buried or removed	x		Date of Backfill Start:			
Has top soil been spread evenly				Noxious weeds removed or sprayed		~	Date of Backfill End:	+	\top	
Has all non-native gravel been buried or removed				Insvasive weeds removed or sprayed	\vdash	2	Yards Hauled Out:	_		
Has pit liner been removed				Contouring complete	×	-	Impacted Soil Hauled To:	+		\vdash
Has all trash been removed			-	Top soil spread	×		Yards Hauled In:	+	_	
Have all weeds been removed	_			Diversions clean and functional	×		Fresh Soil Hauled in From:	+	-	
Teardrop allows vehicle access to all facilities				Silt trap clean and functional		×	Approval to backfill	+	_	\vdash
Drainage ditches allow adequate run off			\vdash	Cattle guard / gates removed		×	Back fill mechanically compacted	_	+	-
All non-traffic areas disked properly				Cellar / mouse hole covered .	×	_	Facilities reset	+	+	$\overline{}$
All non-traffic areas seeded			H	Erosion under control	×	_	Trash and debri removed	_	-	
Seeded areas have been mulched			H	Location properly ripped	×		Close Out Completed	+	+	\vdash
			\vdash	Location properly disked	-	_	Soil Removal Sundry Ready to be Filed	-	+	
Noxious weeds have been removed or sprayed			Н		×	_	Soil Relijoval Sulldry Ready to be Filed	+	-	\vdash
Invasive weeds have been removed or sprayed	_		\blacksquare	3.	X				-	
Barriers set to deter traffic				Photo transect installed		×				
Silt traps are functional				Access road properly closed	X					
Culverts are functional				Public use controlled	X					
Upper diversion is functional				Barriers in place		×				
Have wellhead guards and jersey barriers been removed				Grazing controlled		×				
Have reclamation pictures been taken				P&A marker installed & legible	x				\top	
Growth at least 70%		1	\vdash	Well sign removed	×	-		+	+	-
Agency Inspection Date:		-	\vdash	Growth at least 70%	×	-		+	+	-
Sundry is ready to file			\vdash	Trash and debris removed from location	×	_		-	+	\vdash
Sulfully is ready to file	-	-	H	Final reclamation photos taken	-	_		+	-	\vdash
	_	_			×	_		+	_	\vdash
ı	_	_		Agency Inspection Date: 12/28/16	×			_		\perp
		FAN Ready to be filed	X							
Comments:				Comments: Enterprise P/L on site but off Lease, File for FAN			Comments:			

1.