


NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm



BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test	rator: Enervest Operating, LLC API #30-039-05995
Property Name: <u>Jicarilla Cont. 148</u> Well No <u>. 07</u> Location: Unit: <u>P_Section: _15_Township: _25N_Range: 5W</u>	
Well Status(Shut-In or Producing) Initial PSI: Tubing 20 Intermediate Casing 235 Bradenhead	
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH	
PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
TIME 5 min 235	Steady Flow
10 min 0 235	Surges
15 min 0 235	Down to Nothing
20 min	Nothing
25 min	Gas
30 min	Gas & Water
	Water
If bradenhead flowed water, check all of the descriptions that apply below:	
CLEAR FRESH SALTY_	SULFUR BLACK
5 MINUTE SHUT-IN PRESSURE BRADENHEAD O INTERMEDIATE	
REMARKS:	
	- Yes
By William	Witness COMPLY C
Prodition Williess Prodition Williess Williess WEATLURE TO AD TED WAS ALLURE TO AD TED	
(Position) E-mail address	Witness ***FAILURE TO COMPLITED ****FAILURE TO COMPLITED *****FAILURE TO COMPLITED ******FAILURE TO COMPLITED ***********************************