

## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

CIL SCHOLDS DIST. 3

DEC G C 2.13

## BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test Q - 9 - 16 Operator	: Enervest Operating, LLC API #30-039-06121
Property Name: <u>Jicarilla Cont. 147</u> Well No <u>. 01</u> Location: Unit: <u>A_Section: 8_Township: 25N_Range: 5W</u>	
Well Status(Shut-In or Producing) Initial PSI: Tubing 55 Intermediate Casing 60 Bradenhead	
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH	
PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
TIME 5 min 0 60	Steady Flow
10 min 0 62	Surges
'5 min 0 1 64	Down to Nothing
20 min	Nothing
25 min	Gas
30 min	Gas & Water
Water	
If bradenhead flowed water, check all of the descriptions that apply below:	
CLEAR FRESH SALTY	SULFURBLACK
5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE	
REMARKS:	
TUBE TO CO TEST	
REMARKS:  ****FAILURE TO COMPLY  ****TH BRADENHEAD TEST	
By Witness WITH BRANDUM DATED WITH BRANDUM 2016 WITH BRANDUM 2016 Probleman (Position)	
E-mail address	