

NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

GIL CCIIS, CIV DIST. 3 DEC O D 2015 F

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410 (505) 334-6178 FAX: (505) 334-6170 http://emrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test <u>9-28-16</u> Operator: <u>Enervest Operating, LLC</u> API #<u>30-039-08062</u>

Property Name: Jicarilla A ____ Well No. 04 Location: Unit: K_Section: 19 Township: 26N_Range: 5W

Well Status(Shut-In or Producing) Initial PSI: Tubing 52 Intermediate ____ Casing 74 Bradenhead ____

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

		PRESSURE				FLOW CHARACTERISTICS		
Testing		Braden	head	INTE	RM	BRADENHEAD INTERMEDIATE		
	BH	Int	Csg	Int	Csg			
TIME 5 min_	0		75			Steady Flow		
10 min_	6		77			Surges		
15 min_	0	\	80			Down to Nothing		
20 min_						Nothing		
25 min_						Gas		
30 min_						Gas & Water		
						Water		
If bradenhead flowed water, check all of the descriptions that apply below:								
	CLEA	R	FRESH		SALTY	SULFUR BLACK		
5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE								
REMARKS:								
		79.5				E TO EAD TED		
						THUBENNE DE 10		
By_L	Nul (Posit) em a	~		Witnes: *****FAILURE TO COMPLEXIED Witnes: ****FAILURE INHEADENDUM LA2016 WITNES: ****		
E-mail a	ddress							