

NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District ill/3distric.htm

CIL CC113, 517 6187, 3 DEC 0 9 2016

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

(540)	ant I copy to doo've address)
Date of TestOpe	erator: Enervest Operating, LLC API #30-039-31175
Property Name: <u>Jic. Apache 102</u> Well No <u>. 8M</u> Location: Unit: <u>L</u> Section: <u>3</u> Township: <u>26N</u> Range: <u>4W</u>	
Well Status(Shut-In or Producing) Initial PSI: Tubing 70 Intermediate Casing 127 Bradenhead	
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH	
PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
TIME 5 min 0 127	Steady Flow
10 min 6 129	Surges
15 min 0 131	Down to Nothing
20 min_	Nothing ×
25 min_	Gas
30 min_	Gas & Water
Water	
If bradenhead flowed water, check all of the descriptions that apply below:	
CLEAR FRESH SALTY SULFUR BLACK	
5 MINUTE SHUT-IN PRESSURE BRADENHEAD O INTERMEDIATE	
REMARKS: Slight puff	
COMPLY	
By Witness Witness *** *FAILURE TO COMPLY WITH BRADENHEAD TEST (Position) E-mail address	
L-man address	-