

NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

CIL GOLD, DTV DIGT, 6

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410 (505) 334-6178 FAX: (505) 334-6:

(505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/District III/3distric.htm

DEC 0 0 20.5

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test Or	perator: Enervest Operating, LLC API #30-039-06594
Property Name: <u>Jic. Apache 102</u> Well No. 14 Location: Unit: <u>F_Section: 9 Township: 26N Range: 4W</u>	
Well Status(Shut-In or Producing) Initial PSI: Tubing 20 Intermediate Casing 41 Bradenhead 5	
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH	
PRESSURE Testing Bradenhead INTERM	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
TIME 5 min 6 4 4 5	Steady Flow
10 min 0 43	Surges
15 min 0 46	Down to Nothing
20 min	Nothing
25 min	Gas
30 min	Gas & Water
	Water
If bradenhead flowed water, check all of the descriptions that apply below:	
CLEAR FRESH SALT	YBLACK
5 MINUTE SHUT-IN PRESSURE BRADENHEAD O INTERMEDIATE	
REMARKS:	OMPLY
	****FAILURE TO COMPLY ****FAILURE TO COMPLY WITH BRADENHEAD TEST WITH BRADENHEAD TEST WITH BRADENHEAD TABLE W
	****FARADENIM DATE
By Wall Jal	****FAILURE TO SA TEST ****FAILURE TO SA TEST WITH BRADENHEAD TEST FEBRUARY 1,2016
Prod, Foreman	
(Position) E-mail address	