



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONS. DIV. DIST. 3

DEC 09 2016

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10/28/16 Operator: Enervest Operating, LLC API # 30-039-24311

Property Name: Bear Canyon Well No. 08 Location: Unit K Section: 14 Township: 26N Range: 2W

Well Status (Shut-In or Producing) Initial PSI: Tubing 9 Intermediate Casing 9 Bradenhead 4.0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>4.0</u>		<u>9</u>		
10 min	<u>0</u>		<u>9</u>		
15 min	<u>0</u>		<u>9</u>		
20 min	<u>0</u>		<u>9</u>		
25 min	<u>0</u>		<u>9</u>		
30 min	<u>0</u>		<u>9</u>		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE

REMARKS:

Shut Down Pump Jack

2 seconds Blew to 0

By Jason Campbell

Witness

LEASE OPERATOR
(Position)

E-mail address

******FAILURE TO COMPLY
WITH BRADENHEAD TEST
MEMORANDUM DATED
FEBRUARY 1, 2016**