



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
[http://emrhd.state.nm.us/ocd/District IV3district.htm](http://emrhd.state.nm.us/ocd/District%20IV3district.htm)

**BRADENHEAD TEST REPORT**

(submit 1 copy to above address)

Date of Test 8/31/2014 Operator BMC API #30-039-23213

Property Name EPCmu P-5 Well No. 33 Location: Unit P Section 5 Township 24N Range 1E

Well Status (Shut-In or Producing) Initial PSI: Tubing 30 Intermediate N/A Casing 13 Bradenhead 40

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
5 min	0		13		
10 min	0		13		
15 min	0		13		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	yes	
Surges	no	
Down to Nothing	yes	
Nothing	no	
Gas	yes	
Gas & Water	no	
Water	no	

OIL CONS. DIV DIST. 3  
SEP 14 2016

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE N/A

REMARKS: Had a steady flow for the first 5 min of test then  
Down to nothing

By Berni Velazquez  
Lease operator  
(Position)

Witness \_\_\_\_\_

E-mail address \_\_\_\_\_