Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an
abandoned well. Use form 3160-3 (APD) for such proposals.

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

	Expires. January 31, 2016	
5.	Lease Serial No. NMSF078903	
6.	If Indian, Allottee or Tribe Name	

abandoned wer									
SUBMIT IN 1	7. If Unit or CA/Agree	7. If Unit or CA/Agreement, Name and/or No.							
Type of Well Oil Well	er			8. Well Name and No. GALLEGOS CANYON UNIT 056					
2. Name of Operator Contact: SABRE BEER BP AMERICA E-Mail: sabre.beebe@bp.com			BE		9. API Well No. 30-045-07041				
3a. Address 200 ENERGY COURT FARMINGTON, NM 87401 3b. Phone No. Ph: 970-379			(include area o 5-7530	code)	10. Field and Pool or I BASIN FC/KUT	10. Field and Pool or Exploratory Area BASIN FC/KUTZ PC, WEST			
4. Location of Well (Footage, Sec., T.	, R., M., or Survey Description)			11. County or Parish,	State				
Sec 35 T28N R12W 1650FNL	990FWL			SAN JUAN COL	SAN JUAN COUNTY COUNTY, NM				
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA									
TYPE OF SUBMISSION	N								
□ Notice of Intent	☐ Acidize	☐ Deep	oen	☐ Proc	luction (Start/Resume)	☐ Water Shut-Off			
☐ Notice of Intent	☐ Alter Casing	☐ Hyd	raulic Fractur	ing Rec	lamation	■ Well Integrity			
Subsequent Report ■	☐ Casing Repair	□ New	Construction	□ Rec	omplete	Other			
☐ Final Abandonment Notice	☐ Change Plans	Plug	and Abandor	Tem	porarily Abandon				
-	☐ Convert to Injection	☐ Plug	Back	☐ Wat	er Disposal				
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers a Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be fited only after all requirements, including reclamation, have been completed and the operated determined that the site is ready for final inspection. The Gallegos Canyon Unit 056 well API 30-045-07041 was plugged and abandoned on 7/13/2006. As of 11/14/2016 BP has completed reclamation work to include equipment removal, re-contouring, and seeding of location. On December 8, 2016 Sabre Beebe, BP and Randy McKee, BLM performed a site visit to evaluate the reclamation work performed. Mr. McKee approved all work performed on location and agrees the location is ready for monitoring of re-vegetation. Should you have any questions or concerns regarding this matter please contact Sabre Beebe, BP Compliance Specialist at sabre beebe@bp.com or 970-779-9398.									
Electronic Submission #362747 verified by the BLM Well Information System For BP AMERICA, sent to the Farmington									
Name (Printed/Typed) SABRE BE	EEBE	Title CO	MPLIANCE S	SPECIALIST					
Signature (Electronic S	ubmission)	Date 01/04/2017							
THIS SPACE FOR FEDERAL OR STATE OFFICE USE									
Approved By Sunch N Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to conduct the second of the second o	Office	And willfully	o make to any department or	Date 1/10/13					
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.									