

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3
JAN 25 2017

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6/9/2014 Operator Burlington Resources API # 3004524435
Property Name MCDANIEL B Well No. 1E Location: Unit D Section 17 Township 029N Range 011W
Well Status Flowing Initial PSI: Tubing 200 Intermediate Casing 206 Bradenhead 25

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE						FLOW CHARACTERISTICS	
	BRADENHEAD			INTERM			BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg			
5 min			206				Steady Flow	
10 min			207				Surges	
15 min			207				Down to Nothing Y	
20 min							Nothing	
25 min							Gas	
30 min							Gas & Water	
							Water	

If Bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

If Intermediate flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE Bradenhead 1 Intermediate

REMARKS:

BH blew down in 30 seconds through 1" valve. Received verbal approval from Monica Kuehling @ NMOCD.

Tested By cmckee1 Witness