

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company ConocoPhillips Company	Contact Crystal Tafoya	
Address 3401 East 30th St, Farmington, NM	Telephone No. (505) 326-9837	
Facility Name: SJ 26 Pipeline (SJ 32-8 Unit 218)	Facility Type: Pipeline	
Surface Owner Federal	Mineral Owner Federal (SF-079381)	API No. 30-045-28722

LOCATION OF RELEASE

Unit Letter G	Section 35	Township 32N	Range 8W	Feet from the 2305	North/South Line North	Feet from the 1800	East/West Line East	County San Juan
-------------------------	----------------------	------------------------	--------------------	------------------------------	----------------------------------	------------------------------	-------------------------------	---------------------------

Latitude **36.94081** Longitude **107.64145**

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 67 bbls	Volume Recovered 66.5 bbls
Source of Release Pipeline Water Can	Date and Hour of Occurrence Unknwon	Date and Hour of Discovery 11/6/12 at 11:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? Brandon Powell (OCD) & Sherri Landon (BLM)	
By Whom? Crystal Tafoya	Date and Hour 11/7/2012 at 3:48pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
N/A

RCVD NOV 14 '12
OIL CONS. DIV.
DIST. 3



Describe Cause of Problem and Remedial Action Taken.*

A release of 67bbls of produced water occurred in a water can on the SJ 26 Pipeline and 1/2 bbl was released onto the soil. 66.5bbls was recovered from a water truck. The soil was immediately raked.

Describe Area Affected and Cleanup Action Taken.*

Soil sampling will be conducted and assessed to determine a path forward if necessary.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Crystal Tafoya		Approved by Environmental Specialist: 	
Title: Field Environmental Specialist		Approval Date: 11/27/2012	Expiration Date:
E-mail Address: crystal.tafoya@conocophillips.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 11/12/2012 Phone: (505) 326-9837			

* Attach Additional Sheets If Necessary

n JK 1233252857