

JUL 22 2016



NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-617
<http://www.emnrd.state.nm.us/ocd>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6-26-2016 Operator Energen Resources API # 3003907117

Property Name JICARILLA 89 4 Location: Unit M Section 11 Township 27 Range 3
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 135 Intermediate N/A Casing 149 Bradenhead 115

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Intermediate	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor	Flowed	Flowed
5 minutes	24	151	N/A			Steady Flow	☒
10 minutes	13	152	N/A			Surges	
15 minutes	6	152	N/A			Down to Nothing	
20 minutes	6	153	N/A			No Flow	
25 minutes	5	153	N/A			Gas	☒
30 minutes	5	154	N/A			Gas and Water	
5 minute SI	21	154	N/A			Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear ☐ Fresh ☐ Salty ☐ Sulfur ☐ Black ☐

5 Minute Shut-in Bradenhead 21 Intermediate N/A

REMARKS:

BH maintains a very slight flow throughout the test

By [Signature]
Field Foreman
(Position)

Witness _____



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONS. DIV DIST. 3

JUL 22 2016

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-617
<http://www.emnrd.state.nm.us/ocd>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7-26-2016 Operator Energen Resources API # 3003907117

Property Name JICARILLA 89 4 Location: Unit M Section 11 Township 27 Range 3
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 135 Intermediate N/A Casing 149 Bradenhead 115

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	24	151	N/A			Steady Flow ☒	
10 minutes	13	152	N/A			Surges	
15 minutes	6	152	N/A			Down to Nothing	
20 minutes	6	153	N/A			No Flow	
25 minutes	5	153	N/A			Gas ☒	
30 minutes	5	154	N/A			Gas and Water	
5 minute SI	21	154	N/A			Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear ☐ Fresh ☐ Salty ☐ Sulfur ☐ Black ☐

5 Minute Shut-in Bradenhead 21 Intermediate N/A

REMARKS:

BH maintains a very slight flow throughout the test.

By [Signature]
Field Foreman
(Position)

Witness _____