

Submit 3 Copies To Appropriate District
Office
District I

1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103

Jun 19, 2008

WELL API NO.

30-045-13094

5. Indicate Type of Lease

STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

FEE

7. Lease Name or Unit Agreement Name

Scott

8. Well Number 1

9. OGRID Number

217817

10. Pool name or Wildcat

Basin Dakota

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☒ Other

2. Name of Operator

ConocoPhillips Company

3. Address of Operator

P.O. Box 4289, Farmington, NM 87499-4289

4. Well Location

Unit Letter **K** : **2210** feet from the **South** line and **1470** feet from the **West** line

Section **2** Township **29N** Range **13W** NMPM **San Juan** County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

5447' GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

☒ Location is ready for OCD inspection after P&A

NOTE: This location has a sub-surface P&A marker.

- ☒ All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.
☒ Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.
☐ A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It show the

**OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR
PERMANENTLY STAMPED ON THE MARKERS SURFACE.**

- ☒ The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.
☒ Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.
☒ If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.
☒ All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)
☒ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.

When all work has been completed, return this form to the appropriate District office to schedule an inspection.

SIGNATURE Dollie L. Busse TITLE Staff Regulatory Technician DATE 2/15/2017

Type or print name Dollie L. Busse E-mail address: dollie.l.busse@conocophillips.com PHONE: 505-324-6104

For State Use Only

APPROVED BY: Janet D. Kelly TITLE Compliance Officer DATE 2/17/2017
Conditions of Approval (if any): FV



Final Reclamation Detail and Approval

Date Well P&A'd: 9/13/16

Well Name: Scott 1

Location: Unit Letter K Footages 2220' FSL & 1450' FWL

Sec. 02; T- 029 - N, R - 013 - W; County: San Juan; State: New Mexico

Surface Owner Name: Drake Equine LTD Partnership

Reclamation Detail:

Equipment removed: yes X no _____
(All wellhead surface equipment, tanks, meter runs, piping (removed or capped and abandoned below ground, as appropriate), cathodic equipment, fencing etc.)

Location and road have been re-contoured: yes _____ no X

Erosions / Drainage issues addressed with final reclamation: yes _____ no X

Location seeded according to Surface Owner request: yes _____ no X

Maya McCulloch, agree the final reclamation on the subject well has been satisfactorily performed.

(Surface Owner Name): Drake Equine LTD Partnership

(Address): 2651 Farmington Ave / 2929 Schofield Lane 87401

(Date): February 13, 2017

Signature: Maya McCulloch

Witness: _____

RCC Reclamation Completion				Location Name: <u>Scott /</u>				Date: <u>1-16-2017</u> Revision 1									
AP#: <u>3004513094</u>				UL-Sec-Twn-Rng: <u>K 2 29N 13W</u>				Lat/Long <u>36.754001 - 108.179000</u>									
Surface Owner: <u>FEE</u>				Lease#				County/State: <u>San Juan New Mexico</u>									
Pipeline Owner:				Twin/Co-Locate Well Name & Operator:													
Onsite:			Agency Inspector:			Contractor:			Seed Mix:								
Interim Reclamation			Completed	Incomplete	N/A	Final Reclamation			Completed	Incomplete	N/A	Remediation			Completed	Incomplete	N/A
Have pit sample results been approved						3rd party pipeline removed						Facilities stripped					
Has water been removed from pit						Anchors removed						Certificate of waste issued & approved					
Have pit marker photos been taken						Equipment and piping removed						Depth:					
Has certificate of waste been issued & approved						Power poles removed						Width:					
Have all pit contents been removed						Cathodic protection removed						Length:					
Has sample after content removal been taken						Vegetative cages removed						Date of Excavation Start:					
Is location contoured						CMP's removed						Date of Excavation End:					
Is there 4' of cover over pit						Non native gravel buried or removed						Date of Backfill Start:					
Has top soil been spread evenly						Noxious weeds removed or sprayed						Date of Backfill End:					
Has all non-native gravel been buried or removed						Invasive weeds removed or sprayed						Yards Hauled Out:					
Has pit liner been removed						Contouring complete						Impacted Soil Hauled To:					
Has all trash been removed						Top soil spread						Yards Hauled In:					
Have all weeds been removed						Diversion clean and functional						Fresh Soil Hauled in From:					
Teardrop allows vehicle access to all facilities						Silt trap clean and functional						Approval to backfill					
Drainage ditches allow adequate run off						Cattle guard / gates removed						Back fill mechanically compacted					
All non-traffic areas disked properly						Cellar / mouse hole covered						Facilities reset					
All non-traffic areas seeded						Erosion under control						Trash and debris removed					
Seeded areas have been mulched						Location properly ripped						Close Out Completed					
Noxious weeds have been removed or sprayed						Location properly disked						Soil Removal Sundry Ready to be Filed					
Invasive weeds have been removed or sprayed						Location seeded											
Barriers set to deter traffic						Photo transect installed											
Silt traps are functional						Access road properly closed											
Culverts are functional						Public use controlled											
Upper diversion is functional						Barriers in place											
Have wellhead guards and jersey barriers been removed						Grazing controlled											
Have reclamation pictures been taken						P&A marker installed & legible											
Growth at least 70%						Well sign removed											
Agency Inspection Date:						Growth at least 70%											
Sundry is ready to file						Trash and debris removed from location											
						Final reclamation photos taken											
						Agency Inspection Date:											
						FAN Ready to be filed											
Comments:						Comments:						Comments:					
						<u>P&A marker Not Visible</u> <u>Entire location covered</u> <u>with gravel and perimeter</u> <u>chain link fence</u>											