Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

5.	Lease Serial No.
	NMSF078272C

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

6. If Indian, Allottee or Tribe Name

SUBMIT IN		7. If Unit or CA/Agreement, Name and/or No.					
1. Type of Well Gas Well Oth		8. Well Name and No. LYBROOK 2					
2. Name of Operator DJ SIMMONS INC	Contact: E-Mail: rseale@djs	ALE		9. API Well No. 30-039-23995-00-S1			
3a. Address FARMINGTON, NM 87499	3b. Phone No. (include area code) Ph: 505-326-3753			10. Field and Pool or Exploratory Area LYBROOK			
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description,)			11. County or Parish, State		
Sec 4 T23N R7W NESE 1700 36.253036 N Lat, 107.571884				RIO ARRIBA COUNTY, NM			
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICA	ΓE NATURE OI	F NOTICE, R	REPORT, OR OTH	ER DA	TA
TYPE OF SUBMISSION	ACTION						
✓ Notice of Intent	☐ Acidize	☐ Deep	en	☐ Productio	n (Start/Resume)	e)	
	☐ Alter Casing	☐ Hyd	raulic Fracturing	ing Reclamation		☐ Well Integrity	
	□ Casing Repair	□ New	Construction	☐ Recomple	olete		ner
☐ Final Abandonment Notice	☐ Change Plans	Plug	and Abandon	□ Temporar	rily Abandon		
	☐ Convert to Injection	☐ Plug	Back	☐ Water Di	sposal		
					OIL CON	IS. DIV	V DIST. 3 4 2017
14. I hereby certify that the foregoing is	Electronic Submission #3	357683 verifie	d by the BLM Wel sent to the Farmin	I Information	System		
Commit	ngton I on 02/22/201	7 (14TLS0312SE)					
Name (Printed/Typed) RODNEY		Title AGENT					
Signature (Electronic S	Submission)		Date 11/10/20	016			
Signature (Electronic C	THIS SPACE FO	R FEDERA			E		
Approved By ACCEPT	ED		ABDELGA TitlePETROLE	DIR ELMANI UM ENGINEI		Д	Date 02/22/2017
Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent would entitle the applicant to conduct the applicant the applicant to conduct the applicant to conduct the applicant to conduct the applicant to conduct the applicant the applicant to conduct the applicant		Office Farming	ton				
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent				willfully to mak	e to any department or a	agency of	f the United
(Instructions on page 2) ** BLM REV	ISED ** BLM REVISED	** BLM RE	VISED ** BLN	I REVISED	** BLM REVISED) **	

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 Farmington, New Mexico 87499 505-325-2627 *fax: 505-325-1211

DJ Simmons Inc. Lybrook 2

1

October 24, 2016 Page 1 of 1

1700' FSL and 370' FEL, Section 4, T-23-N, R-7-W Rio Arriba County, NM Lease Number: NMSF078272C API #30-039-23995

Plug and Abandonment Report
Notified NMOCD and BLM on 10/18/16

Plug and Abandonment Summary:

- Plug #1 with CR at 5122' spot 65 sxs (76.7 cf) Class B cement at 15.6 ppg with 1.18 cuft/sx yield from 5122' to 4266' to cover the Gallup Interval and cover Point Lookout, 1st 4 bbls displaced mixed with 1.5 gallon corrosion inhibitor. Tag TOC at 4267'.
- Plug #2 with 28 sxs (33.04 cf) Class B cement at 15.6 ppg with 1.18 cuft/sx yield from 3127' to 2758' to cover the Mesaverde top, 1st 1.5 bbls displaced mixed with 1 gallon corrosion inhibitor.
- Plug #3 with 40 sxs (47.2 cf) Class B cement at 15.6 ppg with 1.18 cuft/sx yield from 2215' to 1688' to cover the Fruitland top.
- Plug #4 with 28 sxs (33.04 cf) Class B cement at 15.6 ppg with 1.18 cuft/sx yield from 1667' to 1298' to cover the Kirtland and Ojo Alamo tops, 1st 4 bbls mixed with 1.5 gallon corrosion inhibitor.
- Plug #5 with 30 sxs (35.4 cf) Class B cement at 15.6 ppg with 1.18 cuft/sx yield from 332' to surface to cover the 8-5/8" shoe and surface circulate good cement out 4-1/2" casing valve.
- Plug #6 with 34 sxs Class B cement at 15.6 ppg with 1.18 cuft/sx yield through poly pipe to top off casings and install DHM plate with coordinates 36° 15' 12" N / 107° 34' 20" W.

Plugging Work Details:

- 10/20/16 Road rig and equipment to location. Spot in and RU. Open up well; no pressures. RU relief lines. Dig out bradenhead valve and install 2" plumbing to surface. Spot in matting board. ND wellhead. MU 8-5/8" companion flange. NU BOP and function test. TOH and tally 120 jnts 2-3/8" 4.7# J-55 tubing. SI well. SDFD.
- 10/21/16 Travel to location. Held safety meeting. Check well pressures: SITP 20 PSI, SICP 80 PSI and SIBHP 0 PSI. Blow well down. Function test BOP. TOH and tally 53 jnts 2-3/8" 4.7# J-55 tubing, total tally 5634.64'. LD SN and perf sub. Tubing had heavy scale last 950' and last 200' had rotted couplings. Round trip A-Plus 4-1/2" string mill to 5122'. PU 4-1/2" DHS CR and set at 5122'. Circulate well clean. Attempt to pressure test casing, unable. Spot plug #1 with calculated TOC at 4266'. SI well. SDFD.
- 10/24/16 Travel to location. Held safety meeting. Open up well; no pressures. Function test BOP. Tag TOC at 4267'. Pressure test casing to 800 PSI, OK. Spot plugs #2, #3, #4 and #5. TOH and LD all tubing. ND BOP and dig out wellhead. Write Hot Work Permit. Cut off wellhead. Found cement down 32' in 4-1/2" casing and down 9' in 8-5/8" casing. Spot plug #6 Class B cement through poly pipe to top off casings and install DHM plate with coordinates 36° 15' 12" N / 107° 34' 20" W. RD and MOL.

Rick Romero, NMOCD representative, was on location.

