



NEW MEXICO ENERGY, MINERALS  
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 9/19/16 Operator Merrion Oil Gas Corporation API # 3003927235 <sup>3003929235</sup> <sub>2-22-17</sub>

Property Name Featherstone Federal 2 (MV) Location: Unit      Section 19 Township 26N Range 02W  
(Well Name and Number)

Pressure (Shut-in or Producing)      Tubing 170 Intermediate      Casing 200 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Intermediate	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor	Flowed	Flowed
5 minutes	0	200	N/A			Steady Flow	
10 minutes	0	202	N/A			Surges	
15 minutes	0	204	N/A			Down to Nothing	
20 minutes	0	206	N/A			No Flow	✓
25 minutes	0	208	N/A			Gas	
30 minutes	0	210	N/A			Gas and Water	
5 minute SI						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear N/A Fresh N/A Salty N/A Sulfur N/A Black N/A

5 Minute Shut-in Bradenhead C Intermediate     

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

**\*\*\*\*FAILURE TO COMPLY  
WITH BRADENHEAD TEST  
MEMORANDUM DATED  
FEBRUARY 1, 2016**

OIL CONS. DIV DIST. 3

FEB 24 2017

By Kyle Davis  
Pumper

Witness     

(Position)

NMOCD Test Area: C

1

1200  
10/10