Submit One Copy To Appropriate District Office	State of New Mexico		Form C-103	
District I	Energy, Minerals and Natural Resources		Revised November 3, 2011 WELL API NO.	
1625 N. French Dr., Hobbs, NM 88240 District II	OIL CONCEDUATION DIVISION		80-031-20767	
811 S. First St., Artesia, NM 88210 District III	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.		5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505		STATE FEE	
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Santa I C, I WI 67505		11 240	
87505	DEC AND DEPORTS ON WELL		7. Lease Name or Unit Agreement Name	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A				
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		STATE		
	1. Type of Well: Oil Well Gas Well Other		8. Well Number 27	
2. Name of Operator		9. OGRID Number 185239		
3. Address of Operator		10. Pool name or Wildcat		
P.O. BIX SOZ, ALBUO, NIM		CHARO WASH MU		
4. Well Location				
Unit Letter : 940 feet from the 1 line and 1945 feet from the line				
Section 28 Township 20N Range 9W NMPM County WENNLOY				
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INT	PLUG AND ABANDON	REMEDIAL WOR	SEQUENT REPORT OF:	
_				
PULL OR ALTER CASING	MULTIPLE COMPL			
OTHER:				
OTHER:				
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.				
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the				
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR				
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR				
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.				
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and				
other production equipment.				
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with				
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed				
from lease and well location.				
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)				
All other environmental concerns have been addressed as per OCD rules.				
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-				
retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well				
If this is a one-well lease of last i	emaining wall on lease; all alacte	igal comica nalas an	d lines have been removed from lease and well	
location, except for utility's distribution		ical service poles and	d lines have been removed from lease and well	
location, except for utility's distribution	on infrastructure.			
	on infrastructure.			
When all work has been completed, re	on infrastructure.	District office to sch	nedule an inspection.	
location, except for utility's distribution	on infrastructure. eturn this form to the appropriate TITLE	District office to sch	nedule an inspection.	
When all work has been completed, re	on infrastructure.	District office to sch	nedule an inspection.	
When all work has been completed, residual signatures.	on infrastructure. eturn this form to the appropriate TITLE	District office to sch	redule an inspection. 16 None PE Sold Sold Sold Sold Sold Sold Sold Sold	
When all work has been completed, residually signatures. SIGNATURE TYPE OR PRINT NAME For State Use Only	on infrastructure. eturn this form to the appropriate TITLE	District office to sch	redule an inspection. 16 None Phone: 414-8548	
When all work has been completed, residually of the SIGNATURE TYPE OR PRINT NAME	on infrastructure. eturn this form to the appropriate TITLE	District office to sch	DATE 3/24/2017	
When all work has been completed, residually signatures. SIGNATURE TYPE OR PRINT NAME For State Use Only	on infrastructure. eturn this form to the appropriate TITLE	District office to sch	redule an inspection. 16 None Phone: 414-8548	