



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 10-MAY-2017 Operator UNOCO BURLINGTON API # 30-0 39-20106

Property Name SAN JUAN 28-6 Well # 77 Location: Unit 6 Sec 27 Twn 28 Rge 5

Land Type:

State _____
Federal _____
Private _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas _____
Pressure observation _____

Temporarily Abandoned Well (Y/N): _____ TA Expires: _____

Casing Pres. _____
Bradenhead Pres. _____
Tubing Pres. _____
Int. Casing Pres. _____

Tbg. SI Pres. _____
Tbg. Inj. Pres. _____

Max. Inj. Pres. _____

Pressured annulus up to _____ psi. for _____ mins. Test passed/failed

REMARKS: A BRIDGE PLUG WAS SET AT 8074

THE CASING WAS PRESSURED UP TO 615 AND PRESSURE
HELD FOR THE ENTIRE TEST

By V A H VICTOR A. HENTON
(Operator Representative)

Witness [Signature]
(NMOCD)

Wellsite Supervisor
(Position)

OIL CONS. DIV DIST. 3

MAY 10 2017

Revised 02-11-02