

RECEIVED
MAY 5 2017

Form 3160-5
(February 2005)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0137
Expires: March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE – Other instructions on page 2.

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator
WPX Energy Production, LLC

3a. Address
PO Box 640 Aztec, NM 87410

3b. Phone No. (include area code)
505-333-1816

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
SHL: 1999' FNL & 2478' FWL, Sec 13, T23N, R9W
BHL: 2385' FSL & 2291' FEL, Sec 11 T23N, R9W

5. Lease Serial No.
N0-G-1312-1856

6. If Indian, Allottee or Tribe Name

7. If Unit of CA/Agreement, Name and/or No.
NMNM-135216A

8. Well Name and No.
W Lybrook Unit 712H

9. API Well No.
30-045-35776

10. Field and Pool or Exploratory Area
Lybrook Mancos W

11. Country or Parish, State
San Juan, NM

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other <u>Final Casing</u>
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleation in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

4/26/17-MIRU

4/27/17- Psi Test W/ Antelope Services: Shell Test High 2,000 Psi for 30 Min: Well Head Connection, 7" intermediate Casing, Blind Rams, Kill Valves, Relief side Valves, Stinger flex hose, All outer Valves in Choke Manifold, Low 250 psi for 5 Min: Well Head Connection, 7" intermediate Casing, Blind Rams, Kill Valves, Relief side Valves, Stinger flex hose, All outer Valves in Choke Manifold, all tested good and recorded on chart.

Drilling ahead 6-1/8" lateral

4/28/17- TD 6-1/8" lateral @ 12,095' (TVD 4,856').

4/29/17- Run Production Casing Liner, 154 jts & 3 Pup jts of 4.5", 11.6# P-110, CSG set @ 12094', LC @ 12045', TOL @ 5151', RSI @ 12023' Cement 4.5" Casing Liner with 35% excess figured (Halliburton Services) 6,000 Psi Test on Lines Flush Water @ 8.3# {10 BBLS}, followed by Tuned Spacer @ 11.5# {40 BBLS}, followed by Primary Cement @ 13.3# {158 Bbbs/655 sks followed by Displacement Totaling 147 Bbbs {40 Bbbs MMCR & 80 Bbbs of 2% KCL} Land Plug 2000 PSI & Bump up to 2,487 PSI & Hold 5 min Floats Held got 1 Bbl Back on Bleed off Plug Down 04/29/2017 10:40 Set ZXP Pack off w/ 50 K, Pull up off and Quick Psi Test of Packer Seals with Pump Truck, Good Test, Sting out of Liner Hanger, W/ Pump truck Circ Out 22 Bbl Good Cement to Surface

Run Tie Back Frac String, 114 jts & 2 pups of 4.5", 11.6# P-110, LT&C O'GL to 5,151' MD TOL, Landed on Mandrel Pressure Test Tie Back Backside @ 1,500# for 30 min, good test recorded on Antelope Services chart. Rig Released 4/29/2017 20:00hrs Will report 4-1/2" test on completion paper work.

14. I hereby certify that the foregoing is true and correct.

Name (Printed/Typed)

Lacey Granillo

Title Permit Tech III

Signature

Date 05/01/2017

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

NMOCDAV

OIL CONS. DIV DIST. 3

MAY 05 2017