



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnrd.state.nm.us/ocd/District III/3district.htm>

OIL CONS. DIV DIST. 3
MAY 04 2017

BRADENHEAD TEST REPORT
(submit 1 copy to above address)

Date of Test 5-4-17 Operator Domunion API #30-0 31-05217
Property Name HSU Well No. 36 Location: Unit 5 Section 36 Township 18 Range 9
Well Status (Shut-In or Producing) Initial PSI: Tubing _____ Intermediate _____ Casing Open Bradenhead _____

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
5 min					
10 min					
15 min					
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD _____ INTERMEDIATE _____

REMARKS: dug 4 1/2 feet to concrete. No Bradenhead
Casing open

By [Signature]
(Position)

Witness [Signature]

E-mail address _____