



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

APR 25 2017

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-25-17 Operator Dominion API #30-0 31-20 805

Property Name Hsu Well No. 99 Location: Unit _____ Section _____ Township _____ Range _____

Well Status(Shut-In or Producing) Initial PSI: Tubing _____ Intermediate _____ Casing _____ Bradenhead _____

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME					
5 min					
10 min					
15 min					
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE _____ BRADENHEAD _____ INTERMEDIATE _____

REMARKS:

clug 5.1 feet - no bradenhead

Well, Sits N.E. of 98
By Ralph Ramirez Jr.
Field Supervisor
(Position)

took picture
Witness Monica Luchkins

this well is drilled.

E-mail address _____