



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3district.htm>

OIL CONS. DIV DIST. 3
MAY 02 2017

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5/2/2017 Operator Burlington API #30-0 39-07657

Property Name San Juan 29-7 Unit Well No. 80 Location: Unit 9 Section 9 Township 29 Range 7

Well Status (Shut-In or Producing) Initial PSI: Tubing 115 Intermediate 10 Casing 118 Bradenhead 8.5

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
5 min	0	10	119	0	120
10 min	0	10	119	0	120
15 min	0	10	119	0	120
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	X
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

BH through 1", blew down in 20 sec. Int through 1" blew down in 30 sec

By Mario Villa
(Position)

Witness Janet P. Kelly

E-mail address _____