



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

OIL CONS. DIV DIST. 3
MAY 10 2017

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 4-19-17 Operator Thompson API # 30-037-23406
Property Name Eserita Caldera Pit #27 Location: Unit 4 Section 19 Township 24N Range 7W
(Well Name and Number)
Pressure (Shut-in or Producing) _____ Tubing 1 Intermediate _____ Casing 61 Bradenhead 3

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>61</u>	<u>61</u>					
10 minutes	<u>61</u>	<u>61</u>					
15 minutes	<u>0</u>	<u>61</u>				<u>X</u>	
20 minutes							
25 minutes							
30 minutes							
5 minute SI	<u>63</u>	<u>61</u>					
						Steady Flow	
						Surges	
						Down to Nothing	
						No Flow	
						Gas	
						Gas and Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 3 Intermediate _____

REMARKS:

By

Mike Wagoner
Lease Operator

(Position)

Witness _____